

SERVICE INVOICE

VIN 007 2 C 7 W D G B G 7 F R 6 1 4 1 5 7				DATE #1 07/13/2020
015	MAKE DODGE	MODEL GRAND CARA	COLOR O	TIME #1 17:13
MILES IN 146740	MILES OUT 146741	FIRST USE 00/00/00	LIC MO 0A1-005	CLOSED 16:39
SEE ALSO				08/14/2020
H: (816) - W: (816) -				WRITER GIBSON\20

(1) CHECK TRANSMISSION SHIFT

CHECKED AND REPLACED TRANSMISSION WITH
REBUILT UNIT - REPLACED CONDENSOR/COOLER
EVACUATE, CHARGED, AND DYED A/C - FILLED WITH
FLUID - TEST DROVE

Labor	T27	85
R8090720AH	(TRANSMISSION)	1
850	(4677782AC/COND)	1
850	(5005204AG/HOSE)	1
YN12D	(OIL - COMPRESS)	1
3716	(AC DYE)	1
06810	(TRANSMAX ATF+4)	3
Total Labor		
Total Parts		
Total Repair (Customer)		

(27- KINNEY-) A

Next Service JAN '21 Lube-Oil-Filter

X

Page 1 of 1

Job 24007

24007

24007

Customer Copy
Labor Rate 99.00

W/C	INT.	CUSTOMER
.00	.00	Labor
.00	.00	Parts
.00	.00	Sublet/Fees
.00	.00	Shp. Sup.
.00	.00	Oil/Grease
.00	.00	Sub Total
.00	.00	Tax
.00	.00	Total (Due)

3997.35

Ch