

E 4 F S 0 B D B 0 7 2 0 0

MODEL ECONOLINE COLOR O
FIRST USE 00/00/00
LICENSE 00/00/00

DATE 03/13/2019
TIME 08:08
PRO 14:55
03/27/2019
WRITER

(1) CHECK ENGINE LIGHT ON

SCANNED COMPUTER FOR CODES - P0302,304,457,30
0 - CHECKED - BURNING COOLANT AND OIL
REPLACED ENGINE WITH REBUILT UNIT - REPLACED
1 COIL - FILLED WITH COOLANT - REPLACED PCV
VALVE - TOPPED OFF ALL FLUIDS - TEST DROVE

Labor	T27 252
9C2Z6006CARM (SERVICE ENGINE)	1
3W7Z12029AA (COIL ASY - IGN)	1
8819002 (WIRETIES)	1
FL820SB12 (FILTER ASY - O)	1
E69Z18D434A (COUPLING ASY)	2
5202 (#4 MINI CLAMP)	1
5597016 (FULL INS. BLUE)	1
5598016 (TERMINAL)	1
5232 (#32 CLAMP)	1
XT5QMC (FLUID - TRANSM)	1
VC7B (ANTI-FREEZE)	3
7L3Z6A666A (VALVE ASY)	1
Total Labor
Total Parts
Total Repair (Customer) 7368.02

Next Service JUN '19 Lube-Oil-Filter

.00	.00 Labor
.00	.00 Parts
.00	.00 Sublet
.00	.00 Shp. Sup.
.00	.00 Oil/Grease
.00	.00 Sub Total
.00	.00 Tax
.00	.00 Total (Due) 7388.02