

Date

5/31/2024

COPY

P.O. Number	TERMS	MILEAGE	VIN#
RED/BLACK FREIGHTLI...	Due on receipt	321,593	CSBH2482

Quantity	Item Code	Description	Price Each	Amount
	Complaint	Work to be done: GET TRUCK RUNNING, CHARGE AND CHECK BATTERIES, PM SERVICE, SCREW FIRE EXTINGUISHER BRACKET TO FLOOR AND RE-INSTALL FIRE EXTINGUISHER IN BRACKET, KEY SWITCH IN DASH DONT STAY TIGHT - FIX, RE-INSTALL PLASTIC PIECE IN VISOR AREA ABOVE DASH, FIX DASH PANEL THAT IS LOOSE ON PASSENGER SIDE BY FEET, REMOVE CB COX CABLE AND ANTENNA FROM CAB - TRASH, CHECK AND FIX A/C, DOT INSPECTION		0.00T
1	DW01731 GTN	WINDSHIELD		
1	GLASS LABOR	GLASS LABOR INSTALL		
1	337572	SCREW		
1	BT-31S91	BATTERY STUD STYLE 950 CCA (Needs Core)		
10	26681	CABLE TIE		
6	26684	CABLE TIE		
2	261173	HOSE DIVIDER TIE		
2	TL/60700	GROMMET		
2	ABP/N54A-B9019R	LED LAMP		
3	TL/94993	PIGTAIL		
2	NBSN331	BUTT CONNECTOR		
3	NASN345	BUTT CONNECTOR		
1	26682	CABLE TIE		
1	3157	BULB		
1	TL/28716A	MIRROR ASSEMBLY		
1	ABP/N795-91030	GRILLE ASSEMBLY		
1	502610	#10 HOSE CLAMP		
2	H10112	HOSE PER FOOT		
2	9832	POWER STEERING FLUID PER QUART		
2	1862X6	DOT AIR FITTING		
1	NT20006	TUBING PER FOOT		
1	1469X12	3/4-1/2 MALE ELBOW		
1	1462X12	3/4" BRASS UNION		
3	NT20012	TUBING PER FOOT		
1	NT20008	TUBING PER FOOT		

Total

Date

5/31/2024

P.O. Number	TERMS	MILEAGE	VIN#
RED/BLACK FREIGHTLI...	Due on receipt	321,593	CSBH2482

Quantity	Item Code	Description	Price Each	Amount
1	1868X8X4	DOT PUSH-IN CONN		
1	1868X4X4	DOT PUSH-IN CONN		
1	1869X6	DOT AIR FITTING		
1	3700X4	1/4 BRASS TEE		
1	3220X8X6	1/2-3/8 BUSHING		
1	1480X6X6	3/8-3/8 MALE 45° ELBOW		
6	26683	CABLE TIE		
14	26682	CABLE TIE		
2	FI-W02-377-7215	CAB AIR BAG		
1	TDA/R12102	DRAIN VALVE		
1	3220X6X4	3/8-1/4 BUSHING		
1	3700X6	3/8 BRASS TEE		
2	1868X6	DOT PUSH-IN CONN		
1	1868X4X4	DOT PUSH-IN CONN		
1	14-17797-000	POWER STEERING HOSE		
2	502610	#10 HOSE CLAMP		
2	16-18972-000	TORQUE ROD		
2	FI-W01-377-8536	AIR SPRING		
1	1871X6	DOT AIR BRAKE FITTING		
1	1471X6	BRASS FITTING		
1	1868X4X6	DOT PUSH-IN CONN		
1	1868X10	DOT PUSH-IN CONN		
1	3200X8X6	1/2-3/8 ADAPTER		
5	26682	CABLE TIE		
5	26681	CABLE TIE		
2	KNG/2430HD	MUD FLAP HD		
1	BTS/B703000NTSK	MUD FLAP HANGERS - STAINLESS STEEL (Per Box)		
1	BTS/RT25	REFLECTIVE STRIP (STRAIGHT)		
8	90132	3/8 BOLT		
8	94310	3/8 NYLON NUT		
16	95010	5/16 FLAT WASHER		
1	FON/CCR-PLATE...	5TH WHEEL DISC LEFT		
1	FON/CCR-PLATE-R	5TH WHEEL DISC RIGHT		
1	DN/P551008	COOLANT FILTER		

Total

Date

5/31/2024

P.O. Number	TERMS	MILEAGE	VIN#
RED/BLACK FREIGHTLL...	Due on receipt	321,593	CSBH2482

Quantity	Item Code	Description	Price Each	Amount
1	DN/P551011	FUEL FILTER		
1	DN/P550954	FUEL FILTER (TRI-PAC)		
1	DN/P551005	OIL FILTER		
10	DEO 15W-40 BULK	SYN. BLEND MOTOR OIL PER GALLON		
1	DN/P618478	AIR FILTER		
1	337552	SCREW		
1.75	75W90 Maxtron Syn	Synthetic Gear Lube - per gallon		
1	WWS	BUG CLEANER & WASHER FLUID		
2	Final Charge	Red Coolant- Extended Life per gallon - bulk		
1	9832	POWER STEERING FLUID PER QUART		
1	A06-22717-001	IGNITION SWITCH		
1	A22-77318-000	LOCK SET		
1	337548	SCREW		
1	337568	SCREW		
1	TDA/S973-011-92...	RELAY VALVE KIT		
1	TDA/R955429	CONNECTOR AND O-RING		
1	TDA/S472-195-02...	ATC ADAPTER		
1	50012	O-RING 1/16		
1	DDE-A0189973145	O-RING		
1	DDE-A5411870080	GASKET		
1	DDE-A4711802720	OIL RETURN LINE		
1	1866X6X6	DOT AIR FITTING		
0.5	R134AJ	R134A PER POUND		
2	409500	OIL-A/C PER OUNCE		
1	BW/K207098	TRAILER CONTROL VALVE		
1	FREIGHT IN	FREIGHT IN		
4	H-459	VACUUM TUBING PER FOOT		
2	26681	CABLE TIE		
1	26722	TUBING CLAMP		
1	26684	CABLE TIE		
1	PDT/CASCFM	FLOOR MATS		
2	22-43130-000	SPEAKER		
2	22181	TERMINAL		
2	22296	SEAL		

Total

Date

5/31/2024

P.O. Number

TERMS

MILEAGE

VIN#

RED/BLACK FREIGHTLI...

Due on receipt

321,593

CSBH2482

Quantity	Item Code	Description	Price Each	Amount
1	COMPUTER SCAN	HOOK UP SCANNER & READ ECM		
1	DDE/23539639	SENSOR KIT		
1	DDE/RA4701500694	EGR ACTUATOR		
1	Core Charge	Core Charge On Part		
-1	Core Charge	Core Charge On Part		
1	502404	#4 HOSE CLAMP		
1	DDE/A4710961769	WASTE GATE REPAIR KIT		
1	502636	#36 HOSE CLAMP		
49.30001	Shop Supplies	Shop Supplies/ per labor hour		
Total				

Date

5/31/2024

P.O. Number

TERMS

MILEAGE

VIN#

RED/BLACK FREIGHTLI...

Due on receipt

321,593

CSBH2482

Quantity	Item Code	Description	Price Each	Amount
49.30001	Mechanic Hours	Mechanic Hours to go over unit and make list of repairs. Have windshield replaced, Remove battery cables and load test batteries, Remove and replace one battery to clean connections and make repairs to small wires to hook up cables and wires and tie up wires. Check out lights on unit and replace lamps and wiring as needed to make all lights work. Check over for air leaks, Remove air lines and fittings to replace air valves and replace fittings and lines to hook up all lines to build air to check for leaks and confirm repairs. Remove air lines from air springs on cab and suspension and replace air springs to swap over fittings and hook up lines to charge with air and check for leaks. Replace torque rods on differentials and torque into place. Replace wear pads on fifth wheel. Change engine oil and filter, Fuel filters, Air filter, Check gear lubes, Hub oil, Lights, Tires and brakes. Grease chassis and drivelines. Remove ignition switch from dash and replace switch assembly to tighten into place and hook up wiring to confirm operation. Check out oil leak and remove oil line to replace with new line to torque into place with new seals and gaskets to run engine and recheck for leaks. Disassemble doors and replace speakers and wiring to confirm operation of radio, Install antenna's on cab, Install floor mats in cab. Hook to trailer and found brake valve leaking for trailer, Remove lines and replace valve to hook up lines and recheck for leaks and confirm operation. Replace hose on windshield washers and confirm operation of system. Scan for engine lights and replace delta pressure sensor, Clean out ports in manifold and replace EGR valve actuator to clear out codes and disassemble turbo waste gate pot to install rebuild kit and hook up lines to perform status test and system cleared. Test drive unit to confirm lights stayed off and unit run as it should. Recover a/c system and perform leak test. Recharge system to confirm operation. Power wash unit and test drive a second time for long distance and found unit to work as it should. Thank You!		
Total				\$13,496.29