	01/25/24	08:03	01		
	Account No	Phone No	years a	1.181	Inv No S2357452
	Tax ID No	rikasi orga	75 m 1		wasty to list of
eary ill are en est nocu povegni an energy of paying the of assi nocus through the supression of	sereing and temporal		ones 1 %1		sperson 549
	Part Licensia Algoritation of the	0074 ##.b	5 X 9*	1 5 3/	67 (10) 6

Listing Councils: For any courts sold be-

tory of the service o

o departure.

Name 19 to Romanica a triba bosed inthe Bosed machine are represed trademine of Bos of Copacity in the College and various alignments on

lifer Walf 'a re-

HRS PIN/EIN WARRANTY DATE 2097314 MT100 Mini Track Lod on 788 B52P11654 personal day during the contract to the second of the contract to the contract t

SEGMENT# 1 C 8540 NA 10/30/23 10/30/23 11/30/23

MAKE READY

CAUSE:

30 OCT 23 788HRS KEY START NO BUCKET NO WARRANTY Found machine looked over machine found the following issues/ missing parts

- 1: Engine has hole in block #3 cylinder looks like connecting rod hit it. will need new engine,
- 2: Fuel tank

laminate inside tank is coming apart will need new fuel

- 3:Gear pump mounting bracket broken in half needs replaced,
- 4: Engine mounting bracket engine side mounting holes are wollowed out and missing hardware needs new isolators and mounting bolts also.
- 5: Tracks + rear idlers are worn down unknown state of other idlers but dont look the best
- 6: Hyd reservoir mount broken and missing hardware 7:

- ITEMS MISSING 1: Cooling fan blade
- 2: Air filter housing and all hoses
- 3: Fuel filter assy (atached to air housing)
- 4: Muffler
- 5: Battery
- 6: Drive and alternator belts
- 7: engine oil dipstick
- 8: Alternator response communa 40 vt ma flanvino monta museumbi de segunt fru de la la cosciosa e gregatir da tagli de
- 9: Missing access covers and skiduplate coverage various various access coverage on the contract of the second

CONTINUED ON PAGE 02

Service of the control of the part of the service o

and by in strong course to diversity

TRAVE I SECOND TO THE SECOND T

Date	Time		Page
01/25/24	22:	08:03	B) 02
Account No	Phone No		Inv No
SALEM052			S2357452
Ship Via		Purchase 0	Order
Tax ID No			
			Salesperson
			549

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

2097314

MT100 Mini Track L

788 B52P11654

MT100

CUTROMER IS SUPPOSED TO BRING IN MISSING PARTS Put together est for repairs machine might need more items depends what customer brings back and if I possibly missed

something.

1 NOV 23 Removed fuel tank from machine and took out to wash bay and washed debris from inside machine. STILL WAITING ON MISSING PARTS THAT CUSTOMER SAID THEY WOULD DROP त्मपुष्रम् वेर्ते ५ म् १५५५५ OFF 31 OCT 23

8 DEC 23 Customer dropped off parts was still missing a few items mainly access covers and hardware.,

CORRECTION:

11 DEC 23 Pulled engine out and set it on table got new engine put on table and started transfering all items to new engine got all parts on engine except for alternator need mounting hardware

Installed new fuel tank into machine prepped exchanger to be installed new hoses,

SENT REQUEST IN TO REPLACE ALL ROLLERS AND IDLERS MOST WONT ROLL OR MOVE AT ALL AND SOME HAVE MISSING HARDWARE. ALSO ORDERED MISSING HARDWARE NEEDED + ACCESS COVERS.

26 DEC 23 Removed all rollers from machine started installing new rollers/idlers MISSING 4 IDLERS STILL ON

WAITING ON FAN SHROUD SHIELD, AND LEFT SIDE DRIVE MOTOR HOSE ALL ON ORDER.

installed all new rollers and hardware replaced drive motor hose put all back together to find the hoses are plumbed wrong reverse ifs forward and vise versa, plumbed hoses into correct spot filled hyd reservoir and started machine drive controls are as should now.

CONTINUED ON PAGE 03

Date	ııme			1090
01/25/24	22:	08:03	(B)	0.3
Account No	Phone No			Inv No
SALEM052				S2357452
Ship Via		Purchase (Order	
Tax ID No				
			Sales	sperson
				549

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

2097314

MT100 Mini Track L

788 B52P11654

MT100

Left side control lever u joint is bad and has lots of slop in it ordered new u joint and linkage joints. 15 JAN 24 18 Jan 24 Installed new linkage u joint and installed under skid plate checked fluid levels and lowereed machine to ground took out to test operate and wash out excess fluid from repairs.

24 JAN 24 Adjusted neutral safety switches, Drained and pulled hyd reservoir out of machine moved fittings to new tank, and prepped to install Replaced HYD return hopse to back of HYD tank 25 JAN 24 Installed new hyd reservoir in machine hooked up all lines filled reservoir primed system and started machine checked for leaks, took machine over to wash bay to wash off excess fluid from repairs. and test operated machine brought to shop secured access covers and greased machine. Put machine on west side of building.

ADDITIONAL DESCRIPTION:

- MAKE READY SALESMAN GUDELIO NEEDED BY NOVERMBER 2023
- TEST, INSPECT, GREASE, WASH, STICKERS
- KEY START ALREADY INSTALLED
- INSPECT/REPLACE ITEMS NEEDED TO MAKE LOADER OPERATIONAL
- NEEDS: REMAN ENGINE, TRACKS

DIESEL DIESEL

FREIGHT-IN AND FI WASHER HARDENED 18EM1224

WASHER HARDENED PLN

SCREW FLNGE HEX 29CM820

SCREW FLNGE HEX CAP

SCREW 31C616 BOLT 5 35C410

Date	Time			
01/25/24	22:	08:03	(B)	04
Account No	Phone No			Inv No
SALEM052				S2357452
Ship Via		Purchase	Order	
Tax ID No				
			Sale	sperson
				549

STK#/FLEET#		HRS PIN/EIN	WARRANTY DATE HRS
2097314	MT100 Mini Track L	788 B52P11654	
	MT100		
35C516		BOLT 10	6
35C624		BOLT	4
5HM38	£	CLAMP, HOSE	2
53DM10	3	NUT HX THDLK PR	1
	NUT HX THDLK P	REAPPL	
6569752		HOSE BULK/FT	1
6575580		GASKET	1
6624289		STRAP, TIE	10
6667352		FILTER, FUEL W/	1
	FILTER, FUEL W	/SEPAR	
6678766		NUT	14 N
6684749		BELT DRIVE 3/V2	1
6686683		BELT, ALT	1
6687262	y"	FILTER, AIR OUT	1
	FILTER, AIR OU	TER	
6687263		FILTER, AIR INN	1
	FILTER, AIR IN	NER 4	4.
6691082	4.0	ISOLATOR	4 S
6691268	- 1	MOUNT	1
6733378	The State of the S	BOLT	6 N 4
6734953	-1	COVER	4
6734997	oti-	STRAP TANK	1 N
6735052		MOUNT PUMP	1 N
6735062		HOSE LOWER	1 N
6735750		TANK, HYD	1 N
6736133		HOSE	1 N
6736961		PANEL FAN SHROU	1 N
6737692		BEARING ROLLER	2
6983128		ANTIFREEZE/COOL	3
	ANTIFREEZE/COOL	· ·	
			COMMITTED ON DACE OF

CONTINUED ON PAGE 05

Date	Time			Page
01/25/24	22:	08:03	(B)	05
Account No	Phone No)		Inv No
SALEM052				S2357452
Ship Via		Purchase	Order	
Tax ID No				
			Sales	sperson
				549

STK#/FLEET#			HRS	PIN/EIN	W	ARRANTY	DATE	HRS	
2097314	MT100 Mini	Track L	788	B52P11654					
	MT100								
7CM1260			BOLT		1				
7025626			VENT, B	REATHER	1				
7108113		i,	HOSE		1	N			
7109055		334	COVER		1				
7132697			MOUNT		2	N			
7259181			RING, C	OMPRESSI	2				
7271923			TRACK,	RUBBER	2	S			
7272631			JOINT,	UNIVERSA	1	N			
7273691			GROMMET	•	2	A			
7275547			"SEAL,		_	N			
7279133				DRAULIC		N			
7346228REM				D902 24.		N 4			
7354882				40 GAL 1	1				
7358131			ROD END			N			
7420899		3.00		EX HD 10	28				
7422386				ASSEMBLY	9 500	N			
7422387				SSEMBLY	. 2				
7422388				SSEMBLY	2				
7423415		100	4.	EL ASSEM	2 1	N			
7461579		and the last of th	- proprietor	ND PRIME	1502	-			
7486192		13	VG68 1	T'	1				
7486193		675	100	OIL HAD	1				
83D6			NUT 5	19 Mg	14				
84G3712			BOLT 5		8	3.74			
					3	11.)			
				19%					
	1420	0050			SEGM	ENT TO			

Date	,,,,,,			9 -
01/25/24	22:	08:03	(B)	06
Account No	Phone No			Inv No
SALEM052				S2357452
Ship Via		Purchase	Order	
Tax ID No				
			Sale	sperson
				549

STK#/FLEET#

2097314

MT100 Mini Track L

MT100

HRS PIN/EIN 788 B52P11654

I/EIN WARRANTY DATE

HRS

INTERNAL

CUSTOMER

INTERNAL TOTAL 11525.62