

<i>Fleet #</i>	<i>Make</i>	<i>Model</i>	<i>Year</i>
END DUMP			
<i>Serial #</i>	<i>Customer PO#</i>	<i>Fleet Owner</i>	
END DUMP			

<i>Description of Service</i>	<i>Labor Hours</i>	<i>Labor Rate</i>	<i>Extended Amount</i>
1 CHECK CYLINDER, MAY NEED RESEALED OR COULD JUST NEED TIGHTENED. LET BRENDA KNOW AFTER CHECKING REMOVED CYLINDER FROM TRAILER AND WASHED. EXTENDED AND FOUND VERY BAD SCRATCHES ON SMALL SECTION OF CYLINDER. THERE WERE MANY LIGHT SCRATCHES ON THE OTHER STAGES. CUSTOMER BROUGHT IN NEW CYLINDER. INSTALLED NEW CYLINDER, HAD TROUBLE WITH THE TOP PIN DUE TO THE POST PLUG HITTING THE FRONT WALL. PER CUSTOMER INSTRUCTIONS GROUND OFF PLUG. TESTED FUNCTIONS A FEW TIMES AND ALL WORKED WELL. REMOVED AND REPLACED ONE HOSES ALSO.			

<u>Part Number</u>	<u>Part Description</u>
T2040-1621	JIC FEMALE 16-16
T2090-1616	NPT MALE
T3016D	HOSE 1in ISOBARIC 3100 # WP R17 DIEHARD COVER

Labor	
Material	
Shop Charges	
Tax	
Invoice Total	1,377.04

DATE	SERVICE	DESCRIPTION	QTY
06/17/2023	LEAF SPRING BIG HANGER BOX	338-374	2
	LEAF SPRING EQUALIZER.	338-378	2
	BOLT	334-317	2
	NUT,	334-319	2
	BOLT ASSY	334-343	4
	LEAF SPRING SMALL HANGER BOX	338-375	1
	W/S IR46305	Wheel Seals Trailer	3
	RK4707QSTD23M	4707 Brake Pads / Trailer	3
	HUB CAP.	18010629 / 4009	1
	Oil - 80/90 Gear Oil	F78005	1
	24 Tall	11R24 TIRE	1
	Brake Clean / W7340	Brakleen	6
	Tire Disposal	Tire Disposal	1
	Shop Supplies	MISC / METAL / NUT & STUD	1
	Labor/hr	-TRAILER REPLACE REAR SUSPENSION EQUALIZERS & HANGER BOXES. -TRAILER REAR AXLE REPLACE WHEEL SEALS & BRAKE PADS ON BOTH SIDES & 1 WHEEL STUD & HUB CAP. -TRAILER FRONT AXLE RIGHT SIDE REPLACE WHEEL SEAL & BRAKE PADS &	1

DATE

SERVICE

DESCRIPTION

QTY

RATE

AMOUNT

REPLACE A USED TIRE ON
THE
OUTSIDE.

METAL ROUND TRAILER

SUBTOTAL

TAX

TOTAL

BALANCE DUE

\$3,377.20

SG Home end Dump