

INVOICE

2014 Peterbilt - 389 - Cummins ISX15 CM2350 6 CYL
Lic # : Odometer In : 0

Office 417-991-1152

VIN # : 1XPXD49X3 ED218636

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
SEAL, KIT 4965569	1.00			LR REAR STRUC	
GASKET, FLYWHEEL 4393176	1.00			FLYWHEEL RESERFACE	
OIL	10.00			LR CLUTCH ACC	
OIL				Hazardous Materials	
OIL GASKET 4026684	1.00				
GASKET, ACC 5440813	1.00				
BEARING 6306LLUA1C3	1.00				
CLUTCH 122002-35	1.00				
BPTR BPTR621-5	2.00				
BRAKE CLEAN GUNK BC BRAKE CLEAN	1.00				
KIT-ECA INC K4252RX	2.00				
EXHAUST CLAMP, 5" EC50PLA					
Shop Supplies					

Org. Estimate Revisions Current Estimate

Labor:
Parts:
Sublet:
HazMat:
SubTotal:
Tax:
Total: 7,757.75
Bal Due: \$0.00

Customer Number : 528

Payment

JOB: 2014 Peterbilt 389 Cummins ISX15

MILEAGE: 788,689

VIN: 1XPXD49X3ED218636

Invoice Number: 7419

Description	Quantity	Description	Unit Price
Labor	52.4	Unit Towed in. Inframe overhaul with new Cylinder head. Cut counter bore from shim. Replaced Oil cooler and flushed radiator. Replaced coolant hoses and thermostat and thermostat housing. Replaced coolant hose and ECR cooler. Customer supplied cylinder head and overhaul kit.	
Parts for repair	1	3299776 Housing RGLT	
COUNTER BOR...			
Parts for repair	1	2396304 MANIFOLD HOUSING	
Parts for repair	1	2338005 JOIN EXPANS	
Parts for repair	1	2470266 HOSE	
Parts for repair	1	2396807 CLAMPS AS-V-B	
Parts for repair	1	2470055 HOSE	
Oil Rotella 1...	48	QT OF ROTELLA 15W40	
Antifreeze	15	ALL WEATHER A/FRZ GAL	
Coolant Hose	2	GAT 24228 COOLNT HOSE PER FT	
LF691	1	LUBE OIL FILTER	
FF5319N	1	FUEL FILTER	
FS1000N	1	FUEL WATER SEP FILTER	
FREON	2.5	LBS OF FREON	
SS		Shop supplies	