

Date		Time	Page
09/12/23		21:30:56 (B)	01
Account No.	Phone No.	Invoice No.	
Ship Via			
Sales Tax License No.		Federal Exemption No.	
		C14 / 454	

# Service Invoice

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
213027 4930 Sprayer 4930	5448	N04930X006532	04/07/10	

SEGMENT# 1 C D21 NA 08/28/23 08/30/23 09/22/23

Engine oil leak

CORRECTION:

Cleaned off oil mess on side of engine.  
Ran engine at hi idle for 20 minuets to find oil leak.  
Found that engine oil is leaking around air compressor mounting seal.  
Looked up and quoted parts for customer.

LABOR

11102004

SEGMENT TOTAL==>

SEGMENT# 2 C D21 TRAVEL SC 08/28/23 08/29/23 09/22/23

Travel to perform service at your location

CORRECTION:

Completed necessary travel to and from the customer's location for requested service.

SR CALLAG	Zone Location	2
11102004		

SEGMENT# 3 C D21 NA 08/28/23 08/30/23 09/22/23

Left boom

COMPLAINT:

The left boom will not fold in.

CORRECTION:

Operated machine for 30 minuets and could not get it to mimic what the customer complained it was.  
Tried recalibrating boom functions.  
Removed the right and left side inner boom fold valves and swapped them.

CONTINUED ON PAGE 02

# Service Invoice

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
213027	4930 Sprayer	5448	N04930X006532	04/07/10	
	4930				

While switching the valves I found that the wiring harness  
has several exposed wires.  
Looked and quoted parts for customer.

11102004

LABOR  
SEGMENT TOTAL==>

376478

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*  
LABOR  
SERVICE CALL  
FARMPLAN

# Service Invoice

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
213027	4930 Sprayer 4930	5462	N04930X006532	04/07/10	

SEGMENT# 1 C D48 KSPRAY SER 01/19/24 01/30/24 01/31/24

Completed Koenig Care Sprayer Inspection

## COMPLAINT:

BBADF

Left boom won't fold

Engine oil leak

Monitor update - (Reverts back to last field)

RH boom breakaway issue (replace spring) breaks away to easy or don't break away

## CORRECTION:

Checked all safety shielding, decals, and neutral starting interlock system.

Checked engine oil & filters.

Checked engine air filters, intake, exhaust & emission system components, radiator, radiator cap, water pump, hoses, clamps, fan & fan belt, idlers, and engine damper.

Checked fuel tank, cap, filter, water separator, hoses, lines and fittings.

Checked batteries, cables, starting & charging system, electrical wiring, connectors and harnesses.

Checked brakes, steering, transmission shifting, hydrostatic pump, wheel motors, lines & fittings.

Checked all cab operator functions, gauges, displays, heating & AC system & filters, field, road, & warning lights.

Checked hydraulic pump, filter, reservoir, boom valves, cylinders, lines, & hoses.

Checked frame & chassis, axle assemblies, suspension components, boom frames, hinges and shocks, wheels &

CONTINUED ON PAGE 02

# Service Invoice

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
213027	4930 Sprayer	5462	N04930X006532	04/07/10	
	4930				

hardware ladders & hand rails.

Checked solution & rinse tank, strainers, filters, pump & pump drive, hoses, lines & clamps, and foam marker system.

Check sprayer application rate control systems, displays, & system for error codes, solution hoses, clamps & nozzles.

Performed and completed the inspection due on unit.

Filled out all the paper work and completed the quote for unit.

LABOR

11102004

SEGMENT TOTAL==>

337893

# Parts Invoice

ORDER#: 515640

UNIT 1: 4930 Sprayer                      N04930X006532                      4930

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
TY26815	1GAL 80W/90	OILRACK	3	3	3		1		
TY26797	10W30 OIL 5 GAL	OILRACK	1	1	1		1		
X1JS77-12-12	Fitting	HF	2	2	2		1		
X1JS77-16-12	Fitting	HF	2	2	2		1		
X797TC-12	3/4"HP Hyd.Hose	HF	42	42	42		1		
X1JS77-12-12	Fitting	HF	2	2	2		1		
X1JS77-16-12	Fitting	HF	2	2	2		1		

856486

FARMPLAN