

833421

451694

INVOICE

CONT:580-791-2580
CELL:

PAGE 1

YEAR		MAKE/MODEL		VIN		LICENSE		MILEAGE IN/OUT		TAG	
16		FORD EXPLORER						100884/100884		4879	
DEL DATE	PROD DATE	WARR EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV DATE				
01JAN16 DD											
R.O. OPENED		READY		17:00 04DEC24		CASH		31DEC24			

SERVICE ADVISOR:

17:40 04DEC24 14:50 31DEC24
LINE OPCODE TECH TYPE HOURS

A OWNER REPORTS OG OOD POPPING NOISE HEARD IN FRONT SUSPENSION WHILE
DRIVING OR TURNING
600 FRONT END / BRAKES / SUSPENSION / STEERING
2519 WEBB,MARTIN LIC#: 2519

LIST NET TOTAL

2 FB5Z*18183*A BRACKET
8 *W714682*S442 NUT
2 *W520215*S440 NUT - HEX.
4 *W715932*S439 BOLT
4 *W520517*S440 NUT - HEX.
2 *W520517*S440 NUT

PARTS:

LABOR:

OTHER:

0.00

TOTAL LINE A:

1301.44

100884 **1*25470** DIAG 25100 QCMW FRONT UPPER STRUT MOUNT/BEARING
ROUGH, ALSO HAS SLIGHT BRAKE PULSATION AND WARNING LIGHTS ON,, REPLACE
BOTH FRONT UPPER STRUT MOUNT/BEARINGS 25170, 4 WHEEL ALIGNMENT 25200

B** 21S32 - REAR TOE LINK
CAUSE: 21S32

21S32C ADJUST REAR TOE, IF NECESSARY
2519 WEBB,MARTIN LIC#: 2519

W94

1 DB5Z*5A972*U LINK

21S32B REPLACE BOTH REAR SUSPENSION TOE LINKS
2519 WEBB,MARTIN LIC#: 2519

W94

FC: PART#: COUNT:

CLAIM TYPE: 21S32

AUTH CODE:

2519

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
100884 21S32B 25040, 21S32C 25060 PERFORM FSA 21S32 Replace both
rear suspension toe links 21S32B 25040 AND Check alignment and, if
necessary, adjust rear toe 21S32C 25060 QCMW

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

AUTHORIZED SIGNATURE

CUSTOMER COPY

452642

DIFEE

833421

451694

INVOICE

PAGE 2

86

MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG	
16 FORD EXPLORER						100884/100884 T		4879	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PONO	RATE	PAYMENT	INV. DATE		
01JAN16 DD			17:00 04DEC24			CASH	31DEC24		
R.O. OPENED	READY	OPTIONS: ENG:2.3_Liter_TIVCT							
17:40 04DEC24	14:50 31DEC24								

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

C** MACHINE ALL ROTORS - BRAKES PULSATE
600 FRONT END / BRAKES / SUSPENSION / STEERING
2519 WEBB, MARTIN LIC#: 2519
C

4 *W716843*S439 BOLT AND WASHER ASY - HEX.HEAD
4 *W710681*S439 BOLT

PARTS: LABOR: OTHER: 0.00
100884 **T-25300** MACHINE ALL 4 ROTORS 25300 QCMW

CUSTOMER PAY HAZARDOUS WASTE DISPOSAL, FLUIDS & CHEMICALS FOR REPAIR ORD

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	1905.06

452642

INVOICE

PAGE 1

SERVICE ADVISOR: 6085

DEL DATE	16	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
01JAN16 DD		FORD EXPLORER			100888/100888 T	4086
PROG. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
15:29 31DEC24	16:00 21FEB25				CASH	21FEB25
R.O. OPENED	READY	OPTIONS	ENG:2.3_Liter_TIVCT			

LINE OPCODE TECH TYPE HOURS
A ENGINE IDLES VERY ROUGH WHEN PUT INTO GEAR
200 TUNE/DRIVEABILITY/FUEL
3991 LAGALY, TONY LIC#: 3991

LIST NET TOTAL

1 SALVAGE TRANS-A-TO-Z
CORE CHARGE C
1/17/25-A-TO-Z-
1 FB5Z*6038*E INSULATOR ASY
1 BB5Z*6038*P BRACKET - ENGINE FRONT SUPPORT
6 XT*10*BLV OIL - AUTOMATIC TRANSMISSION
200 TUNE/DRIVEABILITY/FUEL
3991 LAGALY, TONY LIC#: 3991

PARTS: INT
LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 3593.59
100888 T=25050 TEST DROVE AND PERFORMED VISUAL INSPECTION. 25050.
THE FRONT ENGINE MOUNT AND THE TRANSMISSION MOUNT RUBBER IS TORN AND
LOOSE. BOTH MOUNTS WILL NEED REPLACED. SUSPECT THE TRANSMISSION IS
CAUSING THE VIBRATION. SEE TSB #22-2287. QCTL

B** REPLACE TRANSMISSION AND 2 MOUNTS
100 QUICK SERVICE/MAINTENANCE/WAITER
4674 BIRKENFELD, DUSTIN LIC#: 4674

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C)
100888 **T=251390** DIAG 25050. FOUND BOTH MOTOR MOUNT AND
TRANSMISSION MOUNT HAD FAILED. TEST DROVE AND VERIFIED TRANSMISSION
FAILURE. TRANSFER PARTS FROM OLD TRANSMISSION TO THE USED TRANSMISSION.
INSTALLED USED TRANSMISSION 251240. INSTALLED NEW ENGINE MOUNT 25100.
TEST DROVE VERIFIED REPAIR ALL OK QCDBAM

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MSC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

833421

452642

INVOICE

PAGE 2

SERVICE ADVISOR: 6085

YEAR		MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG														
16		FORD EXPLORER						100888/100888 T		4086														
DEL. DATE		PROD. DATE		WARR. EXP.		PROMISED		PO NO.		RATE		PAYMENT		INV. DATE										
01JAN16 DD						17:00 31DEC24						CASH		21FEB25										
R.O. OPENED				READY				OPTIONS: ENG:2.3_Liter_TIVCT																
15:29 31DEC24				16:00 21FEB25																				
LINE OPCODE TECH TYPE HOURS																LST			NET			TOTAL		

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

THANK YOU FOR CHOOSING DIFFEE FORD-LINCOLN.
 OUR GOAL IS 100% CUSTOMER SATISFACTION. YOU
 MAY RECEIVE A SURVEY ABOUT TODAY'S VISIT.
 ANYTHING LESS THAN COMPLETELY SATISFIED IS A
 FAILING GRADE. IF YOU CANNOT GRADE US WITH A
 COMPLETELY SATISFIED RESPONSE PLEASE CALL
 PHILLIP DOUGLAS AT 405-262-4546




LINCOLN

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	3911.62

AUTHORIZED SIGNATURE

CUSTOMER COPY



LINCOLN

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	3911.62

AUTHORIZED SIGNATURE

CUSTOMER COPY