

Work Order Listing

Filters: Date range based on - Completed Date; Status - Completed; Equipment - 2018 KOBELCO SK210LC-10-0509 [9947]

Equipment	Serial Number	Work Order ID	Item ID	Date Item Requested	Description	Item Type	Item Status	Item Condition	Completion Date	Readings at WO Completion
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	7744	9679	11/2/2022	9947-perform check list	Repair	Completed	Complete	11/22/2022	Hour Meter: 2,311
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	7744	9680	11/2/2022	9947-check for smoke coming from machine	Repair	Completed	Complete	11/22/2022	Hour Meter: 2,311
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	7745	9681	11/2/2022	9947-PM4	Repair	Completed	Complete	10/31/2022	Hour Meter: 2,311
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	8299	10764	5/27/2023	9947-Engine overhaul	Repair	Completed	Complete	08/15/2023	Hour Meter: 2,435, Hour Meter: 2,435
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	8299	10368	3/27/2023	9947-check for major engine oil leak	Repair	Completed	Complete	06/26/2023	Hour Meter: 2,435, Hour Meter: 2,435
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	9062	11327	8/15/2023	9947-perform engine over haul	Repair	Completed	Complete	01/26/2024	Hour Meter: 2,444
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	9944	12393	2/13/2024	9947-headlights are not working	Repair	Completed	Complete	02/14/2024	Hour Meter: 2,464
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10097	12573	3/6/2024	PM 2	Preventative Maintenance	Completed	Complete	03/15/2024	Hour Meter: 2,520
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10097	12421	2/15/2024	PM 1	Preventative Maintenance	Completed	Complete	03/15/2024	Hour Meter: 2,520
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10236	12732	3/26/2024	9947-NOx control system failure	Repair	Completed	Complete	04/13/2024	Hour Meter: 2,553
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10397	12931	4/15/2024	9947-check for fuel leak	Repair	Completed	Complete	04/16/2024	Hour Meter: 2,560
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10671	13234	5/23/2024	9947-check for popping noise in left final drive	Repair	Completed	Complete	05/31/2024	Hour Meter: 2,640
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10671	13233	5/23/2024	9947-check a/c not cooling	Repair	Completed	Complete	05/31/2024	Hour Meter: 2,640
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10891	13483	6/21/2024	9947 - A/C Recharge	Repair	Completed	Complete	06/21/2024	Hour Meter: 2,804
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	10915	13510	6/25/2024	9947 - AC	Repair	Completed	Complete	06/21/2024	Hour Meter: 2,804
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	11429	14133	9/24/2024	9947-replace blown hydraulic hose	Repair	Completed	Complete	09/24/2024	Hour Meter: 2,804
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	11623	14368	10/31/2024	9947-replace bucket teeth	Repair	Completed	Complete	11/04/2024	Hour Meter: 2,815
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	11625	14372	10/31/2024	9947-check low fuel pressure codes	Repair	Completed	Complete	11/27/2024	Hour Meter: 3,006
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	11625	14371	10/31/2024	9947-check back up alarm not working	Repair	Completed	Complete	11/27/2024	Hour Meter: 3,006
2018 KOBELCO SK210LC-10-0509 [9947]	YQ15S00509	11811	14601	1/17/2025	9947-oil drip	Repair	Completed	Complete	01/17/2025	Hour Meter: 3,068