

Work Order Listing

Filters: Date range based on - Completed Date; Status - Completed; Equipment - 2016 CAT 308-6665 [9801]

Equipment	Serial Number	Work Order ID	Item ID	Date Requested	Item Description	Item Priority	Item Type	Item Status	Item Condition	Completion Date	Readings at WO Completion
2016 CAT 308-6665 [9801]	FJX06665	9284	11586	9/15/2023	track tensioner	3 - High	Repair	Completed	Complete	09/18/2023	Hour Meter: 1,748
2016 CAT 308-6665 [9801]	FJX06665	9341	11635	9/26/2023	track tensioners	3 - High	Repair	Completed	Complete	10/13/2023	Hour Meter: 1,916
2016 CAT 308-6665 [9801]	FJX06665	9368	11651	9/28/2023	9801-wont start	3 - High	Repair	Completed	Complete	10/04/2023	Hour Meter: 1,834
2016 CAT 308-6665 [9801]	FJX06665	10100	12575	3/6/2024	9801-broken key on bucket	3 - High	Repair	Completed	Complete	03/07/2024	Hour Meter: 2,101
2016 CAT 308-6665 [9801]	FJX06665	10124	12600	3/11/2024	9801-check for hydraulic leak	5 - Low	Repair	Completed	Complete	03/11/2024	Hour Meter: 2,106
2016 CAT 308-6665 [9801]	FJX06665	10142	12620	3/12/2024	9801-hydraulic leak	3 - High	Repair	Completed	Complete	03/14/2024	Hour Meter: 2,119
2016 CAT 308-6665 [9801]	FJX06665	10175	12672	3/19/2024	9801 - track wore out missing bushing pins	3 - High	Repair	Completed	Complete	03/27/2024	Hour Meter: 2,151
2016 CAT 308-6665 [9801]	FJX06665	10181	12665	3/19/2024	9801-engine code	5 - Low	Repair	Completed	Complete	03/20/2024	Hour Meter: 2,129
2016 CAT 308-6665 [9801]	FJX06665	10373	12897	4/11/2024	9801-bucket pins and bushings need replaced	5 - Low	Repair	Completed	Complete	05/02/2024	Hour Meter: 2,269
2016 CAT 308-6665 [9801]	FJX06665	10373	12899	4/11/2024	9801-hydraulic leak out of hammer	5 - Low	Repair	Completed	Complete	05/02/2024	Hour Meter: 2,269
2016 CAT 308-6665 [9801]	FJX06665	10373	12898	4/11/2024	9801-thumb bushing need replaced	5 - Low	Repair	Completed	Complete	05/02/2024	Hour Meter: 2,269
2016 CAT 308-6665 [9801]	FJX06665	10377	12908	4/12/2024	9801-check for low power	3 - High	Repair	Completed	Complete	05/02/2024	Hour Meter: 2,269
2016 CAT 308-6665 [9801]	FJX06665	10450	12981	4/22/2024	PM4	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	05/02/2024	Hour Meter: 2,269
2016 CAT 308-6665 [9801]	FJX06665	10682	13255	5/24/2024	9801-adjust tracks	3 - High	Repair	Completed	Complete	05/28/2024	Hour Meter: 2,299
2016 CAT 308-6665 [9801]	FJX06665	10682	13256	5/24/2024	9801-repair hydraulic leak	3 - High	Repair	Completed	Complete	05/28/2024	Hour Meter: 2,299
2016 CAT 308-6665 [9801]	FJX06665	10722	13291	5/29/2024	9801-replace bucket teeth and retainers	5 - Low	Repair	Completed	Complete	05/30/2024	Hour Meter: 2,325
2016 CAT 308-6665 [9801]	FJX06665	10814	13395	6/13/2024	9801-repair ram lock on bucket	5 - Low	Repair	Completed	Complete	06/24/2024	Hour Meter: 2,391
2016 CAT 308-6665 [9801]	FJX06665	11032	13648	7/16/2024	9801-repair quick attach for bucket	5 - Low	Repair	Completed	Complete	07/16/2024	Hour Meter: 2,412
2016 CAT 308-6665 [9801]	FJX06665	11276	13911	8/21/2024	PM1	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	09/03/2024	Hour Meter: 2,534
2016 CAT 308-6665 [9801]	FJX06665	11297	13980	8/28/2024	9801-check for code EID 43 low system voltage	5 - Low	Repair	Completed	Complete	09/03/2024	Hour Meter: 2,534
2016 CAT 308-6665 [9801]	FJX06665	11306	13989	8/29/2024	9801-upper windshield glass broken out	2 - CAPA	Repair	Completed	Complete	12/02/2024	Hour Meter: 2,613
2016 CAT 308-6665 [9801]	FJX06665	11408	14108	9/19/2024	9801 - Aux Hose for Thumb Replacement	5 - Low	Repair	Completed	Complete	09/19/2024	Hour Meter: 2,536
2016 CAT 308-6665 [9801]	FJX06665	11686	14443	12/3/2024	9801-repair hydraulic leak at thumb	5 - Low	Repair	Completed	Complete	12/02/2024	Hour Meter: 2,610
2016 CAT 308-6665 [9801]	FJX06665	11750	14531	12/30/2024	9801- Reinstall track at job 466	1 - Machine Down/Red	Repair	Completed	Complete	12/30/2024	Hour Meter: 2,728