

DATE 05/05/2025  
DUE DATE 06/04/2025

DATE		DESCRIPTION	QTY	RATE	AMOUNT
05/05/2025	Hours	2022 Peterbilt 389 semi truck * VIN: 1XPXP4EX2ND787961 * Check engine light Unit had a check engine light on for DPF pressure differential sensor function. Took tubes off to sensor. The inlet tube was plugged. Cleaned tube and reinstalled it started truck and regen dpf. Drove truck around the yard after repair and the check engine light wasn't on.	2	125.00	250.00
05/05/2025	Mileage		32	4.00	128.00

BALANCE DUE \$378.00