

Work Order Listing

Filters: Date range based on - Completed Date; Status - Completed; Equipment - 2021 GODWIN CD100S-93/02 [6705]

Equipment	Serial Number	Work Order ID	Item ID	Date Item Requested	Description	Item Priority	Item Type	Item Status	Item Condition	Completion Date	Readings at WO Completion
2021 GODWIN CD100S-93/02 [6705]	20090993/02	9151	11351	8/19/2023	PM 1	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	08/29/2023	Hour Meter: 1,421
2021 GODWIN CD100S-93/02 [6705]	20090993/02	9586	11950	11/15/2023	6705-check for no start	5 - Low	Repair	Completed	Complete	11/17/2023	Hour Meter: 1,506
2021 GODWIN CD100S-93/02 [6705]	20090993/02	9587	11813	10/24/2023	PM 1	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	11/17/2023	Hour Meter: 1,506
2021 GODWIN CD100S-93/02 [6705]	20090993/02	10131	12610	3/12/2024	6705-check for not pumping water	3 - High	Repair	Completed	Complete	03/12/2024	Hour Meter: 1,591
2021 GODWIN CD100S-93/02 [6705]	20090993/02	10157	12638	3/14/2024	6705-replace pump belt	5 - Low	Repair	Completed	Complete	03/14/2024	Hour Meter: 1,599
2021 GODWIN CD100S-93/02 [6705]	20090993/02	10526	13071	5/2/2024	6705 - Auto Shut Down	5 - Low	Repair	Completed	Complete	05/09/2024	Hour Meter: 1,624
2021 GODWIN CD100S-93/02 [6705]	20090993/02	10569	13117	5/10/2024	PM 1	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	05/15/2024	Hour Meter: 1,624
2021 GODWIN CD100S-93/02 [6705]	20090993/02	11033	13652	7/17/2024	6705-replace pump belt	5 - Low	Repair	Completed	Complete	07/19/2024	Hour Meter: 1,671
2021 GODWIN CD100S-93/02 [6705]	20090993/02	11407	14107	9/19/2024	6705 - Pump Repair	5 - Low	Repair	Completed	Complete	09/19/2024	Hour Meter: 1,675
2021 GODWIN CD100S-93/02 [6705]	20090993/02	11613	14357	10/30/2024	PM 1	6 - Preventative Maintenance	Preventative Maintenance	Completed	Complete	11/01/2024	Hour Meter: 2,057