

SERVICE INVOICE

Invoice Date 10/31/2022	Invoice No. 01 766876
Customer Order No.	Shipped Via
	Job No.
	Date Completed 10/31/2022
	Work Order No. 111933

Equipment Identification:

Item No. M1DH U

Srl No. 1G91M1310KM119056

Desc 1 M1DH 150GAL DIESEL MELTER

Desc 2 HEATED HOSE

Make

Model

Part No.	Description	Quantity	Unit Price
303 012 000	HEATED HOSE M-SERIES	1.00	
Notes: HEATED HOSE ELEMENT IS BAD JUST REPLACED AT 282 HOURS. 8/5/22			
SERVICE SUMMARY: METER READING: 375 RAN THROUGH OPS, HEATED HOSE GOT TO 75 DEG AND STOPPED HEATING - CHECKED GENERATOR OUTPUT, FOUND 90VAC - OHMED OUT HEATING ELEMENT, FOUND THE ELEMENT IS OPEN. - OHMED A NEW HOSE ELEMENT, FOUND 7.5 OHMS REPLACED HEATED HOSE *HOSE WAS JUST REPLACED 8/5/22 WHEN THE UNIT HAD 282 HOURS ON IT. *BES REPLACED ON WORK ORDER #111933			

SERVICE INVOICE

Invoice Date 8/22/2022	Invoice No. 01 762289
Customer Order No.	Shipped Via
Contract No.	Job No.
	Date Completed 8/16/2022
	Work Order No. 111933

Equipment Identification:

Item No. M1DH U

Srl No. 1G91M1310KM119056

Desc 1 M1DH 150GAL DIESEL MELTER

Desc 2 HEATED HOSE

Make

Model

Part No.	Description	Quantity	Unit Price
409968	HEATED HOSE/DRIPLESS WAND ASSY M-SERIES	1.00	
403910	5 GAL HEAT TRANSFER OIL MODEL 230 TAKES 31 GALS	5.00	
<p>Notes:</p> <p>NEEDS HOSE AND WAND CHANGE HEATING OIL MIKE 605-633-0554</p> <p>SERVICE SUMMARY: METER READING: 282 REPLACED HOSE AND WAND CHANGED HEAT TRANSFER OIL CALL MIKE 605-633-0554</p>			
Miles		Trip	Shop
			Total

SERVICE INVOICE

Invoice Date 7/15/2022	Invoice No. 01 759899
Customer Order No.	Shipped Via
Ordered By	Job No.
	Date Completed 7/15/2022
	Work Order No. 111449

Equipment Identification:

Item No. M1DH U
 Srl No. 1G91M1310KM119056
 Desc 1 M1DH 150GAL DIESEL MELTER
 Desc 2 HEATED HOSE
 Make
 Model

Part No.	Description	Quantity	Unit Price	Extended Price
130097	THERMOCOUPLE (105/225)	1.00		
3405 55	55#/BX 3405 JOINT SEALANT	4.00		
DF	36/PALLET DIESEL FUEL, "DYED" OFF-ROAD ONLY	5.00		
<p>Notes:</p> <p>CUSTOMER SAID MATERIAL TEMP WAS TO HIGH GOT TO 500 DEGREES CHECK OVER CALL BRYAN WITH BILLION 605-595-6198 ANY QUESTIONS GREAT PLACE CONSTRUCTION LLC COMPANY RENTING TO OWN</p> <p>SERVICE SUMMARY:</p> <p>METER READING: 251</p> <p>GOT MACHINE UP TO TEMP TO CHECK OPS OPS SEEMED NORMAL FOR THE FIRST COUPLE HOURS OF OPERATIONS</p> <ul style="list-style-type: none"> - FOUND NO TAR COMING OUT OF THE WAND, BUT THE PUMP SPINS GOOD AND THE BALL VALVE IS MOVING NORMALLY. - REVERSED THE PUMP A COUPLE TIMES AND IT STARTED PUMPING TAR <p>MATERIAL TEMP JUMPED FROM 400F TO 480F ONCE IT STARTED PUMPING THE MATERIAL PROBE IS IN THE PUMP</p> <p>**FOUND CHUNKS IN THE TAR, INLET TO THE PUMP IS PROBABLY PLUGGED</p> <ul style="list-style-type: none"> - IF TAR IS NOT GETTING INTO THE PUMP, THE TEMP READING IS WRONG DUE TO THE BUILDUP INSIDE, THE TAR WILL NEED TO BE DUMPED AND THE OLD HARD TAR CHIPPED OUT. <p>DUMPED OUT THE OLD TAR AND DISPOSED OF IT CHIPPED OUT OLD HARD AND OVERHEATED TAR IN THE POT CLEANED OUT THE MATERIAL PROBE SLOT IN THE POT ITSELF</p>				
	Miles	Trip Charge	Shop Supplies	Total Materials
<p>ALL ITEMS LISTED ABOVE RECEIVED IN GOOD CONDITION. ALL SHORTAGES AND CLAIMS MUST BE REPORTED WITHIN 5 DAYS FROM RECEIPT OF SHIPMENT. ALL RETURNS SUBJECT TO A RESTOCKING CHARGE.</p>			Total Freight	Total Labor
<p>WITH RESPECT TO THE PRODUCTS SET FORTH HEREIN. THERE ARE NO</p>				CONTINUED

100

Equipment Identification:

Srl No. 1G91M1310KM119056

Desc 1 M1DH 150GAL DIESEL MELTER

Desc 2 HEATED HOSE

Make

Model

ALL ITEMS LISTED ABOVE RECEIVED IN GOOD CONDITION. ALL SHORTAGES AND CLAIMS MUST BE RETURNED TO THE SUPPLIER.

SERVICE INVOICE

Invoice Date 7/15/2022	Invoice No. 01 759899
Customer Order No.	Shipped Via
Order No.	Job No.
	Date Completed 7/15/2022
	Work Order No. 111449

Equipment Identification:

Item No. M1DH U

Srl No. 1G91M1310KM119056

Desc 1 M1DH 150GAL DIESEL MELTER

Desc 2 HEATED HOSE

Make

Model

Part No.	Description	Quantity	Unit Price	Extended Price
	<p>REPLACED THE MATERIAL TEMP PROBE</p> <p>- FOUND PART OF AN OLD BALL VALVE HANDLE IN THE PICKUP GRATE</p> <p>PUT IN 4 BOXES OF MATERIAL AND GOT UP TO TEMP</p> <p>STRAINED THE TAR FOR SEVERAL HOURS</p> <p>GOT THE MATERIAL UP TO TEMP AGAIN AND SUCKED BACK THROUGH THE HOSE</p> <p>TAR READINGS ARE ACCURATE NOW, DOES NOT OVERHEAT</p> <p>CALLED BOBBY AND LEFT A MESSAGE 7/15/22</p>		PG DWN	

SERVICE INVOICE

Invoice Date 10/31/2022	Invoice No. 01 766877
Customer Order No.	Shipped Via
Ordered By	Job No.
	Date Completed 10/31/2022
	Work Order No. 112548

Equipment Identification:

Item No. M1DH U
 Srl No. 1G91M1310KM119056
 Desc 1 M1DH 150GAL DIESEL MELTER
 Desc 2 HEATED HOSE
 Make
 Model

Part No.	Description	Quantity	Unit Price	Extended Price
X132400150	FUEL FILTER	1.00		
130431	GENERATOR	1.00		
Notes: DOESN'T STAY LIT REPLACE BURNED OUT LED - CUSTOMER SUPPLIED NEW LED SERVICE SUMMARY: METER READING: 375 CHECKED LED'S REPLACED PUMP GREEN LED LIGHT - CUT OUT THE OLD ONE, AND SOLDERED IN THE NEW ONE. LEDS ALL WORK NOW TROUBLESHOOT NOT STAYING LIT - CHECKED FUSES, OKAY - BURNER FUEL PUMP MOTOR DOES NOT COME ON - REMOVED BURNER CONTROLLER, AND CHECKED POWER. - FOUND 12V ALL THE TIME GOING INTO CONTROLLER, AND 12V ON SIGNAL WIRE WHEN CALLING FOR HEAT WHILE CHECKING CONTROLLER, BURNER MOTOR STARTED AND CONTINUED TO RUN - FLAME WAS CUTTING OUT STILL, LOW FUEL PRESSURE. - REPLACED BURNER FUEL FILTER BURNS CONSISTENTLY NOW. CONTINUED TO CHECK WIRES COMING OUT OF THE CONTROLLER, AND FOUND THE BLACK WIRE GOING TO THE MOTOR LOOSE IN THE WIRE NUT. TIGHTENED THE CONNECTION AND RAN, BURNER CONTINUES TO BURN NOW HEATED HOSE NOT WORKING? PG DWN WHILE TEST BURNING, FOUND HEATED HOSE ONLY GOT TO 100DEG F CHECKED AGAIN THE NEXT DAY, HEATED HOSE NOT WORKING AT ALL CHECKED GENERATOR, FOUND 12V DC GOING IN, AND ONLY 5VAC COMING OUT CHECKED BRUSHES, ALL CHECK OKAY				
	Miles	Trip Charge	Shop Supplies	Total Materials
			Total Freight	Total Labor
			Estimate Fee	Subtotal
			Sales Tax	Invoice Total
				CONTINUED...