

# Invoice

|           |                |
|-----------|----------------|
| Date      | 10/12/2020     |
| Invoice # | 8156           |
| Account # |                |
| Terms     | Due on receipt |

| MDL: MFR: SER #: HRS: |        |  |                  | Rep        | P.O. Number |
|-----------------------|--------|--|------------------|------------|-------------|
| 4850 JD 7121 8900     |        |  |                  |            |             |
| Qty                   | Part # | Description                            | List Price       | Act. Price | Ext. Price  |
| 1                     | BA     | 4850 HY-PERFORMANCE ENGINE KIT         |                  |            |             |
| 1                     | BA     | NEW COMPLETE 6 CYLINDER JD DIESEL HEAD |                  |            |             |
| 1                     | UPS    | HEAD FRT.                              |                  |            |             |
| 1                     | BA     | (RE38666) RADIATOR                     |                  |            |             |
| 1                     | BA     | (R50398) COVER                         |                  |            |             |
| 2                     | BA     | (R50402) RADIATOR HOSE                 |                  |            |             |
| 7                     | BA     | (R88045) CAP SCREW                     |                  |            |             |
| 8                     | BA     | (R88044) CAP SCREW                     |                  |            |             |
| 5                     | BA     | (R88043) CAP SCREW                     |                  |            |             |
| 6                     | BA     | (R88042) CAP SCREW                     |                  |            |             |
| 1                     | BA     | (DZ101880) OIL FILTER                  |                  |            |             |
| 1                     | BA     | (RE29018) BELT SET                     |                  |            |             |
| 1                     | BA     | (AR96371) SHROUD                       |                  |            |             |
| 1                     | BA     | (R79346) HOSE                          |                  |            |             |
| 1                     | BA     | (R76371) RADIATOR HOSE                 |                  |            |             |
| 1                     | BA     | (AT13740) DRAIN VALVE                  |                  |            |             |
| 1                     | BA     | (AR91035) RADIATOR KIT                 |                  |            |             |
| 1                     | BA     | (AR80653) FILTER ELEMENT               |                  |            |             |
| 1                     | BA     | (AR80652) FILTER ELEMENT               |                  |            |             |
| 6                     | BA     | (SE500097) INJECTION NOZZLE REMAN      |                  |            |             |
| 6                     | N21    | RECONDITION RODS                       |                  |            |             |
| 2                     | BA     | (AR86745) FILTER ELEMENT               |                  |            |             |
| 1                     | BA     | (A5203R) HOSE                          |                  |            |             |
| 1                     | BA     | (R76558) SLEEVE                        |                  |            |             |
| 1                     | BA     | (R94447) GASKET                        |                  |            |             |
| 1                     | BA     | (RE19401) SEAL                         |                  |            |             |
| 2                     | BA     | (RE14439) SEAL                         |                  |            |             |
| 1                     | BA     | (RE23146) SEAL                         |                  |            |             |
| 1                     | BA     | (AR56639) OIL PUMP INTAKE              |                  |            |             |
| 1                     | BA     | (R520546) GASKET                       |                  |            |             |
| 1                     | BA     | (AT25038) OIL COOLER                   |                  |            |             |
| 1                     | BA     | (R520645) GASKET                       |                  |            |             |
|                       |        |  | Subtotal         |            |             |
|                       |        |  | Sales Tax (7.0%) |            |             |
|                       |        |  | Total            |            |             |
|                       |        |  | Payments/Credits |            |             |
|                       |        |  | Invoice Balance  |            |             |

# Invoice

|           |                |
|-----------|----------------|
| Date      | 10/12/2020     |
| Invoice # | 8156           |
| Account # |                |
| Terms     | Due on receipt |

| MDL: MFR: SER #: HRS: |            |   |                  | Rep        | P.O. Number |
|-----------------------|------------|---|------------------|------------|-------------|
| 4850 JD 7121 8900     |            |   |                  |            |             |
| Qty                   | Part #     | Description                                 | List Price       | Act. Price | Ext. Price  |
| 1                     | BA         | (L34569) COUPLING                           |                  |            |             |
| 1                     | BA         | (R78202) ISOLATOR                           |                  |            |             |
| 1                     | BA         | (R72739) COUPLING                           |                  |            |             |
| 1                     | BA         | (A4847R) WASHER                             |                  |            |             |
| 1                     | BA         | (R207223) SEALING WASHER                    |                  |            |             |
| 1                     | BA         | (SE500912) WATER PUMP REMAN                 |                  |            |             |
| 1                     | UPS        | PUMP FRT.                                   |                  |            |             |
| 4                     | BA         | (R47153) O-RING                             |                  |            |             |
| 1                     | BA         | (R530687) GASKET                            |                  |            |             |
| 2                     | BA         | (RE524105) GASKET                           |                  |            |             |
| 1                     | BA         | (R73189) BELT                               |                  |            |             |
| 1                     | BA         | (R59747) INTAKE MANIFOLD                    |                  |            |             |
| 1                     | UPS        | MANIFOLD FRT.                               |                  |            |             |
| 1                     | BA         | (R89441) GASKET                             |                  |            |             |
| 6                     | BA         | (122-1023) VALVE SEAL                       |                  |            |             |
| 1                     | BA         | SURFACE HEAD                                |                  |            |             |
| 1                     | BA         | CNC O-RING HEAD                             |                  |            |             |
| 1                     | BA         | CRACK CHECK OLD HEAD                        |                  |            |             |
| 2                     | BA         | CLEAN HEAD, OLD & NEW HEAD                  |                  |            |             |
| 1                     | BA         | R&R VALVES SO THEY COULD CUT O-RING GROOVES |                  |            |             |
| 1                     | HAZ-MH     | MID-HEAD HAZ CHARGE                         |                  |            |             |
| 1                     | RE47336    | 466 JD Cylinder Head Gasket                 |                  |            |             |
| 6                     | 5.011/.105 | HEAD SEAL RING                              |                  |            |             |
| 1                     | R83000     | TURBO Coupling                              |                  |            |             |
| 2                     | BA         | (R73445) SCREW                              |                  |            |             |
| 1                     | R61128     | Line  |                  |            |             |
| 1                     | UPS        | LINE FRT.                                   |                  |            |             |
| 1                     | BA         | (AR72337) CAP                               |                  |            |             |
| 1                     | BA         | (R26286) O-RING                             |                  |            |             |
| 9                     | BA         | (R54500) SCREW                              |                  |            |             |
| 8                     | BA         | (24H1305) WASHER                            |                  |            |             |
| 1                     | BA         | (RE12176) AIR RESTRICTION SENSOR            |                  |            |             |
|                       |            |   | Subtotal         |            |             |
|                       |            |   | Sales Tax (7.0%) |            |             |
|                       |            |   | Total            |            |             |
|                       |            |   | Payments/Credits |            |             |
|                       |            |   | Invoice Balance  |            |             |

# Invoice

|           |                |
|-----------|----------------|
| Date      | 10/12/2020     |
| Invoice # | 8156           |
| Account # |                |
| Terms     | Due on receipt |

| MDL: MFR: SER #: HRS: |              |                        |                         | Rep        | P.O. Number |
|-----------------------|--------------|------------------------|-------------------------|------------|-------------|
| 4850                  | JD           | 7121                   | 8900                    |            |             |
| Qty                   | Part #       | Description            | List Price              | Act. Price | Ext. Price  |
| 1                     | BA           | (RE12466) SUCTION HOSE |                         |            |             |
| 1                     | BA           | (RE24897) FILLER CAP   |                         |            |             |
| 3                     | BA           | (TY22475) CLAMP        |                         |            |             |
| 1                     | BA           | (TY22490) CLAMP        |                         |            |             |
| 1                     | UPS          | CLAMP, SENSOR FRT.     |                         |            |             |
| 1                     | BA           | (RE10982) VALVE        |                         |            |             |
| 1                     | R520526      | Gasket                 |                         |            |             |
| 6                     | BA           | (37H79) SCREW          |                         |            |             |
| 6                     | BA           | (24H1290) WASHER       |                         |            |             |
| 2                     | BA           | (R120722) ABSORBER     |                         |            |             |
| 1                     | 151          | SHOP SUPPLIES & HAZ    |                         |            |             |
| 5.25                  | 15W40BIO     | 15W-40 BREAK IN OIL    |                         |            |             |
| 16                    | HY-GUARD     | HYDRAULIC OIL          |                         |            |             |
| 3.25                  | 134LB        | R134 LB FREON          |                         |            |             |
| 7                     | B30204       | ANTIFREEZE             |                         |            |             |
| 1                     | DYNO         | PTO DYNO TEST          |                         |            |             |
| 8                     | LABOR-JAYMIE | NOTES-BELOW            |                         |            |             |
| 56                    | LABOR-KYLE   | NOTES BELOW            |                         |            |             |
|                       |              |                        | <b>Subtotal</b>         |            |             |
|                       |              |                        | <b>Sales Tax (7.0%)</b> |            |             |
|                       |              |                        | <b>Total</b>            |            |             |
|                       |              |                        | <b>Payments/Credits</b> |            |             |
|                       |              |                        | <b>Invoice Balance</b>  |            |             |

# Invoice

|           |                |
|-----------|----------------|
| Date      | 10/12/2020     |
| Invoice # | 8156           |
| Account # |                |
| Terms     | Due on receipt |

| MDL: MFR: SER #: HRS: |        |   |                         | Rep P.O. Number |            |
|-----------------------|--------|---|-------------------------|-----------------|------------|
| 4850                  | JD     | 7121  | 8900                    |                 |            |
| Qty                   | Part # | Description   | List Price              | Act. Price      | Ext. Price |
|                       |        | FINISH DISASSEMBLE OF ENGINE.<br>CLEAN BLOCK & ALL PARTS<br>HEAD WAS BROKEN BAD SO REPLACED WITH NEW HEAD & BOLTS<br>HAD HEAD O-RINGED SO WE DID NOT HAVE TO TAKE BLOCK OUT OF TRACTOR.<br>HAD CONNECTING RODS REBUILT<br>REPLACED ENGINE OIL COOLER BECAUSE OF SO MUCH SLUDGE IN IT.<br>CLEANED ALL OIL SYSTEM PARTS OF SLUDGE<br>HAD TO CLEAN BLOCK GOOD & FLUSH OUT.<br>OVERHAULED ENGINE WITH NEW HY=PERFORMANCE PISTON KIT, NEW BEARINGS & GASKETS<br>HAD TO FIND OR BUY PARTS THAT HAD BEEN TAKEN OFF TO REASSEMBLE ENGINE<br>INSTALLED NEW AIR & OIL FILTERS<br>RUN ON DYNO TO BREAK IN ENGINE<br>INSTALLED HOOD & SHIELDS |                         |                 |            |
|                       |        |   | <b>Subtotal</b>         |                 |            |
|                       |        |   | <b>Sales Tax (7.0%)</b> |                 |            |
|                       |        |   | <b>Total</b>            | \$19,155.51     |            |
|                       |        |   | <b>Payments/Credits</b> |                 |            |
|                       |        |   | <b>Invoice Balance</b>  |                 |            |

# Invoice

|           |                |
|-----------|----------------|
| Date      | 04/14/2023     |
| Invoice # | 10833          |
| Account # |                |
| Terms     | Due on receipt |

| MDL: MFR: SER #: HRS: |              |                               |                         | Rep P.O. Number |            |
|-----------------------|--------------|-------------------------------|-------------------------|-----------------|------------|
| 4650 JD 9131          |              |                               |                         |                 |            |
| Qty                   | Part #       | Description                   | List Price              | Act. Price      | Ext. Price |
| 1                     | R49866       | Gasket                        |                         |                 |            |
| 6                     | R79605       | WASHER                        |                         |                 |            |
| 1                     | 42382        | AIR FILTER                    |                         |                 |            |
| 12                    | R51936       | Sealing Washer                |                         |                 |            |
| 1                     | 51824        | OIL FILTER                    |                         |                 |            |
|                       |              | USED ROCKER SHAFT - NO CHARGE |                         |                 |            |
|                       |              | 12 USED PUSH RODS - NO CHARGE |                         |                 |            |
| 1                     | 151          | SHOP SUPPLIES & HAZ           |                         |                 |            |
| 5                     | 15W40        | ENGINE OIL-GAL.               |                         |                 |            |
| 22                    | LABOR-SKYLER | NOTES BELOW                   |                         |                 |            |
|                       |              |                               | <b>Subtotal</b>         |                 |            |
|                       |              |                               | <b>Sales Tax (7.0%)</b> |                 |            |
|                       |              |                               | <b>Total</b>            |                 |            |
|                       |              |                               | <b>Payments/Credits</b> |                 |            |
|                       |              |                               | <b>Invoice Balance</b>  |                 |            |

# Invoice

Date 04/14/2023

Invoice # 10833

Account #

Terms Due on receipt

| MDL: MFR: SER #: HRS: |        |   |                  | Rep P.O. Number |            |
|-----------------------|--------|---|------------------|-----------------|------------|
| 4650                  | JD     |   | 9131             |                 |            |
| Qty                   | Part # | Description   | List Price       | Act. Price      | Ext. Price |
|                       |        | TRACTOR CAME IN W/ MISFIRE AND DIESEL IN OIL<br>REMOVED ALL INJECTORS & PRESSURE TESTED. THEY<br>CHECKED OK<br><br>DID COMPRESSION TEST ON ALL CYLINDERS & FOUND<br>CYLINDER #2 HAD LOW COMPRESSION<br><br>REMOVED VALVE COVER - FOUND CYLINDER #2 HAD<br>BROKEN PUSH ROD ON INTAKE VALVE & MULTIPLE LOOSE<br>VALVE LASHES CAUSING MISS FIRE<br><br>FOUND ROCKER SHAFT HAD BROKEN GUIDE PIN & TURNED<br>SO NO OIL WAS GETTING TO ROCKER ARMS<br><br>INSTALLED NEW GUIDE PIN, USED PUSHRODS, & USED<br>ROCKER SHAFT - SET VALVES - TRACTOR RAN REAL GOOD<br>AND GOT RID OF MISFIRE<br><br>RAN TRACTOR FOR SEVERAL HOURS - DID NOT GET<br>DIESEL IN OIL - IT WAS LIKELY CAUSE BY CYLINDER 2<br>MISFIRE<br><br>RESEALED ALL LEAKING RETURN LINES & CHANGED DIRTY<br>AIR FILTER<br><br>WASHED OUT PLUGGED RADIATOR & ENGINE |                  |                 |            |
|                       |        |   | Subtotal         |                 |            |
|                       |        |   | Sales Tax (7.0%) |                 |            |
|                       |        |   | Total            |                 |            |
|                       |        |   | Payments/Credits |                 |            |
|                       |        |   | Invoice Balance  |                 |            |

\$3,019.92