

Date
06/30/25

Time
19:17:22 (B)

Page
01
Invoice No.
W4743049

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
F0010669 9300 4WD Tractor	10386	RW9300H001824	10/08/99	2000
9300				

- ** Buy parts online and view your invoices at RDOequipment.com/account
Create your FREE RDO Account today!
- ** Sign up for parts & service text alerts. Ask us how to get started!

SEGMENT# 1 C MUN01 DIAG 05/12/25 05/12/25

DIAGNOSE oil leak

REPAIR:

- Determined that the oil leak was coming from the rear axle out of the right axle shaft seal.

10401099

LABOR
SEGMENT TOTAL==>

SEGMENT# 2 C MUN01 NA 05/12/25 05/12/25

PARTIAL INSPECTION

CONDITION:

Short inspect

DIAGNOSTICS:

Made list:

- 1) Hyd res fittings leaking, sight glass
- 2) Eng oil pan leaking some
- 3) Aux belt cracked, idler pulley locked up
- 4) Aux belt tensioner, other idlers rough
- 5) Fan bearing loose
- 6) Front axle bearings loose
- 7) Coolant low, water pump, thermostats?
- 8) Engine mounts worn out
- 9) Gudgeon loose
- 10) RH steering hoses
- 11) steering cylinder pins and bushings worn. May need

CONTINUED ON PAGE 02

Thank you for your business

Date
06/30/25

Time
19:17:22 (B)

Page
02

Invoice No.
W4743049

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
F0010669 9300 4WD Tractor 10386 RW9300H001824 10/08/99 2000
 9300

boring.

12) Tractor needs full service

13) Cab mounts

14) Windshield wipers

15) Engine air intake filter housing melted from failed
muffler, backfeeding exhaust air into aspirator and melted
the filter housing.

Needs new muffler and air filter housing.

16) Oil leak from trans somewhere.

PROMOAG

INSPECTION

1-

10401099

SEGMENT# 3 C MUN01 10-050-230 05/12/25 05/12/25

REAR AXLE R&R, FINAL DRIVE R&R AND RECONDITION

CONDITION:

Both final drives

REPAIR:

-Washed rear of machine

-Drained oil from rear axle

-Removed tires from rear axle

-Removed rear axle and washed

-Fully disassembled rear axle final drives and inspected
parts

- Determined that the rear axle needed full rebuild.

Customer did not want to fix anything. Assembled in reverse
order.

NOTE!!! Parts on return cart

JD10134

BEARING CONE

2 0

CONTINUED ON PAGE 03

Thank you for your business

Date
06/30/25

Time
19:17:22 (B)

Page
03

Invoice No.
W4743049

SERVICE INVOICE

STK#/FLEET#

F0010669 9300 4WD Tractor
9300

HRS PIN/EIN
10386 RW9300H001824

WARRANTY DATE
10/08/99

HRS
2000

PM38657
RE168641
TY22028
TY26101

SEALANT
SEAL
HY-GARD TM
BRK/PRTS CLNR
Cleaning Solvent
3" Brown Disc

3 0
2 0
7
2
2

0898887

10401099

SEGMENT TO

SEGMENT# 4 C ALM01 8015D 05/12/25 05/12/25
WHEELS, DUAL, R&R, TWO (SAME AXLE)

CONDITION:

Remove rear wheels and install rear wheels.

DIAGNOSTICS:

Remove and install rear wheels

REPAIR:

Support machine off the ground

Use hoist to remove wheels and weights

Install Inside weights

Install inside dual

Inside outer wedges

install outer dual

Torque spec is 445 FT LBS

TY22028

HY-GARD TM

10401099

SEGMENT# 5 C MUN01 NA

05/12/25 05/12/25

CONTINUED ON PAGE 04

Thank you for your business

Date
06/30/25

Time
19:17:22 (B)

Page
04

Invoice No.
W4743049

Ship Via

SERVICE INVOICE

STK#/FLEET#

F0010669 9300 4WD Tractor
9300

HRS PIN/EIN
10386 RW9300H001824

WARRANTY DATE HRS
10/08/99 2000

R&I rockshaft and drawbar

10401099

LABOR

SEGMENT TOTAL==>

***** WORK ORDER TOTALS *****

PARTS

LABOR

HAUL CHARGE

SUB TOTAL==>

FERGUS FALLS City

MN STATE TAX

OTTER TAIL CO TR Special

TOTAL DUE RDO

10907.46

Thank you for your business