## Service Invoice

Invoice Date Call Number Location Page SI000626862 4/9/2025 SC00802722

1/3

Invoice Account 0607460		<b>Due Date</b> 5/10/2025		
Customer PO Customer EQ	Model 938G	Serial Num 4YS02158	nber Equipm CU0087	
	Sı	ummary		
Parts Labor Misc Parts, Labor and Misc Flat Rate All Total		LAKE COUN	ax Summary  ITY TRANSIT SALES TAX 0.5: A STATE SALES TAX 6.875%	
Sub total Shop Supplies and Environmental Fees		Sales Ta	ax	\$50.0302732-cet
Sub total		Total		\$ 1,207.15
			Invoice Date Account	SI000626862 4/9/2025
			Amount Due:	
			Amount Enclosed:	

 Invoice
 Date
 Call Number
 Location
 Page

 SI000626862
 4/9/2025
 SC00802722
 Duluth
 2 / 3

SC00802722-001 Troubleshoot - Hydraulic System

Customer complaint: ( LOCATION , TWO HARBORS , LAKE COUNTY ) THERES A HYDRAULIC OIL LEAK FRONT OF

MACHINE

Resultant damage: OIL LEAKING

Cause of failure: THE LINE RELIEF VALVE HAD RUSTED THREW

Repair process comments: ORDERED THE PARTS AND THE CUSTOMER INSTALLED THEM

Customer PO	Customer EQ	Model 938G	Serial Number 4YS02158	Equipment ID CU0087242	Segment SMU
Quantity Type	Part Number	Description		Unit Price	Amount
1.00 Parts	1086428	Valve Gp			
2.00 Parts	1860908	Valve Gp			
6.00 Parts	8F0212	Seal O Ring			
Labor		Labor		Parts Subtotal	
				Labor Subtotal	

SC00802722-001 Troubleshoot - Hydraulic System

Parts Labor Misc

Segment Subtotal

 Invoice
 Date
 Call Number
 Location
 Page

 SI000626862
 4/9/2025
 SC00802722
 3 / 3

SC00802722-002 Troubleshoot - Engine

Customer complaint: ( LOCATION , TWO HARBORS , LAKE COUNTY ) FUEL IN THE COOLANT ,

Resultant damage: FUEL IN COOLANT

Cause of failure: INJECTOR COPPER NUMBER 2 WAS LEAKING

Repair process comments: THE CUSTOMER HAD REMOVED ALL THE INJECTORS, I PRESSURIZED THE SYSTEM

AND FOUND THE LEAK THE CUSTOMER WAS GOING TO DO THE REPAIR

Customer PO Customer EQ Model Serial Number Equipment ID Segment SMU 938G 4YS02158 CU0087242

Quantity Type Part Number Description Unit Price Amount Labor

Labor Subtotal

SC00802722-002 Troubleshoot - Engine Parts
Labor
Misc
Segment Subtotal

		~~
		)
		_

# Service Invoice

Invoice Date Call Number Location Page SI000576311 12/3/2024 SC00686228

1/5

Invoice Account 0607460			100		e Date 0/2025
Customer PO	Customer EQ	Model 938G	Serial Number 4YS02158	Equipment ID CU0087242	Segment SML
		Sum	mary		
Parts abor Misc			Sales Tax Sun LAKE COUNTY TRANS MINNESOTA STATE S	SIT SALES TAX 0.500%	
Parts, Labor and I					
Sub total Shop Supplies and Environmental Fe			Sales Tax	81505	
Sub total			Total		\$ 6,461.54
			Invo Date Acce		SI000576311 12/3/2024 0607460
			Amo	ount Due:	
			Amou	nt Enclosed:	1- 00

Invoice	Date	Call Number	Location	Page
SI000576311	12/3/2024	SC00686228		2/5

SC00686228-001 Troubleshoot - Engine
Customer complaint: ( LOCATION , TWO HARBORS , LAKE COUNTY ) COOLANT WAS COMING OUT THE EXHAUST Resultant damage: LEAKING COOLANT INTO EXHAUST

Cause of failure: HEAD GASKET

Repair process comments: I TROUBLE SHOT IT AND THE CUSTOMER HAD REPLACED THE ENGINE I SET THE RACK

AND THE TIMING AND VLAVES

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		938G	4YS02158	CU0087242	
Quantity Type	Part Number	Description		Unit Price	Amount
4.00 Parts	6V5683	Bolt			
1.00 Parts	5P9806	Seal-O-Ring			
1.00 Parts	8H7521	Seal-O-Ring			
6.00 Parts	0R8867	Inject0R Gp			
6.00 Parts	0R8867CC	Inject0R Gp - Core C			
1.00 Parts	1T1639	Ring			
1.00 Parts	1628756	Control As			
1.00 Parts	0R1011	Pump As Wtr			
1.00 Parts	0R1011CC	Pump As Wtr - Core	C		,
8.00 Parts	3718119	Cm Hose Bulk			
1.00 Parts	612501	Element As			
1.00 Parts	612502	Element As			
1.00 Parts	1265869	Regulator			
1.00 Parts	4W0549	Gasket			
1.00 Parts	1363884	Hose			
1.00 Parts	1363885	Hose			
12.00 Parts	1416348	Bolt Hex Hea			
2.00 Parts	7N5683	Dowel			
1.00 Parts	7C7705	Hose			
-6.00 Parts	0R8867WC	Inject0R Gp - Worn C	;		
1.00 Parts	7C3615	Hose			
1.00 Parts	1085746	Hose			
1.00 Parts	7W5340	Gasket			
2.00 Parts	3P1156	Seal-O-Ring			
1.00 Parts	9S8005	Pług			
1.00 Parts	3500081 - 147	<b>ENGINE HEATER - 1</b>	500		
1.00 Parts	1180666	Hose As			
1.00 Parts	1R0753	Filter As			
-1.00 Parts	0R1011WC	Pump As Wtr - Worn	С		
1.00 Parts	10R0395	Motor Gp Ele			
1.00 Parts	10R0395CC	Motor Gp Ele - Core			
1.00 Parts	7E5189	Valve			
1.00 Parts	3N3252	Spring			
1.00 Parts	5P7813	Seal			

oice SI000576311		Date 12/3/2024	Call Number SC00686228	Location	<b>Page</b> 3 / 5
1.00 Pa	rts 1367227	Se	eal O Ring		
1.00 Pa	rts 1291101	Va	alve Gp		
-1.00 Pa	rts 10R0395WC	Mo	otor Gp Ele - Wom		
					Parts Subtotal
Lai	bor	La	bor		
					Labor Subtotal
					Parts
SC006	86228-001	Troubleshoo	ot - Engine		Labor
			-		Misc
1					Segment Subtotal

Invoice	Date	Call Number	Location	Page	
SI000576311	12/3/2024	SC00686228		4/5	-

## SC00686228-002 Troubleshoot - Differential

Customer complaint: ( LOCATION , TWO HARBORS , LAKE COUNTY ) DRIVE TRAIN MAKING NOISE

Resultant damage: NOISE WHEN TURNING

Cause of failure: U-JOINTS

Repair process comments: OPERATED THE MACHINE, FOUND THAT THE UJOINT WERE MAKING NOISE, THE

CUSTOMER HAD CHANGED THE OIL ALREADY . ORDERED THE PARTS FOR THE CUSTOMER AND HE

PERFORMED THE WORK

Customer PO	Customer EQ	Model 938G	Serial Number 4YS02158	Equipment ID CU0087242	Segment SMU
Quantity Type	Part Number	Description		Unit Price	Amount
10.00 Parts	4E5985	Bolt			
6.00 Parts	4E3273	Strap			
1.00 Parts	3526990	Accumulator			
3.00 Parts	5766565	Univ Jt-Gd			
1.00 Parts	8H7521	Seal-O-Ring			
1.00 Parts	4S8598	Screen As			
1.00 Parts	6F7062	Washer			
1.00 Parts	8T0293	Bolt			
1.00 Parts	3685063	Tube AsMag			
Labor		Labor		Parts Subtotal  Labor Subtotal	
SC006862	228-002 Troubl	eshoot - Differenti	al	Parts Labor Misc Segment Subtota	

<b>voice</b> SI000576311		ate 2/3/2024	Call Number SC00686228	Location	Location Page 5 / 5	
SC00686228-0	003 Travel To/F	rom - N	lachine			
Customer PO	Customer		<b>lodel</b> 38G	Serial Number 4YS02158	Equipment ID CU0087242	Segment SMU
Quantity Type Labor	Part Number		<b>description</b> abor		Unit Price	Amount
					Labor Subtotal	
40.00 Misc	MIL	т	RAVEL MILEAGE			
					Misc Subtotal	
					Parts Labor	
SC006862	228-003 Tra	vel To/F	rom - Machine		Misc	_
					Segment Subtota	al

			,
			·-
			J

## Long block Includes

- Block
- Rods
- Piston assemblies
- Cylinder head
- Gear housing & front seal

### Oil cooler

- Crankshaft
- Valve train
- Camshaft
- Gasket set
- Oil pump

### WARRANTY COVERAGE

1 Year Unlimited Milage

Core

Core

Core

Freight/Shipping

Shipping

NA

Core Freight/Shipping

Core Shipping

NA

**Untaxed Amount** 

Taxes

Total \$ 13,213.95

# Quotation # S232856

**Quotation Date:** 

08/19/2024

Expiration:

09/18/2024

**Customer Equipment:** 

\_ther | N/A

			and the second of the second o		
Part #	Description	Condition	Unit Price	Quantity	Amount
64F4L072SB	Long Block	Reman Exchanged			