

REPAIR ORDER WO004154

RO Date: 10/7/24
 Internal RO:
 Print Date: 10/9/25, 2:14PM Page: 1 / 1

Description: TRACTOR		Location:	
Year: 2020		VIN #: 1XPBDP9LD679008	
Unit #: 795		Engine #: A396544	
License: 28KR8R		PMCVI:	
Unit Owner: DITZFELD TRANSFER INC		Make/Model: PACCAR/MX 12.9L 380-	
Last Cert. Date:		PTRB/579	
Last Service:			
Odometer 530023	MI		
Thermo 12354	HR		

<u>Activity Description</u>	<u>Task</u>	<u>Sys</u>	<u>Asm</u>	<u>Reason</u>	<u>Est.Hours</u>
1. Radiator - Engine Cooling System	24	042	002	1	0.00
INSTALLED NEW RADIATOR					
Activity Created By: C6581MANAGER					

<u>Part Number</u>	<u>Item Description</u>	<u>Core</u>	<u>Failure</u>	<u>Act.Qty.</u>
2401892	RADIATOR		No Failure	1.00 EA
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

There are no notes for this facility

REPAIR ORDER WO004444

RO Date: 1/10/25
 Internal RO:
 Print Date: 10/9/25, 2:12PM Page: 1 / 1

Description: TRACTOR	Location:
Year: 2020	VIN #: 1XPBDP9LD679008
Unit #: 795	Engine #: A396544
License: 28KR8R	PMCVI:
Unit Owner: DITZFELD TRANSFER INC	Make/Model: PACCAR/MX 12.9L 380-
Last Cert. Date:	PTRB/579
Last Service:	
Odometer 549759 MI	

<u>Activity Description</u>	<u>Task</u>	<u>Sys</u>	<u>Asm</u>	<u>Reason</u>	<u>Est.Hours</u>
1. Engine Assembly	24	045	020	1	0.00
KC PETERBILT INSTALLED NEW HEAD ON AIR COMPRESSOR					
Activity Created By: C6581MANAGER					

<u>Part Number</u>	<u>Item Description</u>	<u>Core</u>	<u>Failure</u>	<u>Act.Qty.</u>

There are no notes for this facility