

SERVICE INVOICE

INVOICE NUMBER: WO3A0008198
Invoice Date: 05-06-24

Due \$94,801.90

Make AA
Model D8T
Serial# 0FMC00829
Equip No 30215
Machine ID
Meter Reading 5.0
PSO/WO MR04023

Customer #	PO #	Doc Date	Salesman	Division	Store	Terms
7550932	13851-30215	04-01-24	589	G	3A	2
Quantity	Item	Description	Unit Price	Extension		

180.00

TRAVEL M LEAGE

TOTAL MISC CHGS SEG 88

SEGMENT 88 TOTAL

ENVIRO. FEE

TEXAS STATE TAX
ODESSA/ ECTOR CO TAX
ECTOR CO HOSP DIS TAX

INVOICE TERMS NET 30

Parts

Labor

Misc.

Tax

TOTAL \$94,801.90

INVOICE #	EMPS6000503
Client PO #	FMC0829
Client #	2512850
Invoice Date	06-08-23
AGMT/PSO/WO #	00C654896
EM - MESA	P

MAKE	MODEL	SERIAL NUMBER	EQUIPMENT NUMBER	METER READING	MACH. I.D. NUMBER
AA	D8T	0FMC00829	18-013		
QUANTITY	ITEM	*NONRETURNABLE	DESCRIPTION	UNIT PRICE	EXTENSION

PARTS SALES PERSON: COMMERCE ORDER
 IF YOU HAVE QUESTIONS ABOUT THIS INVOICE, PLEASE CALL THE
 DEPARTMENT THANK YOU FOR YOUR BUSINESS.

1	20R-5261	*BLOCK G LONG	N
1	20R-5261	*CORE DEPOSIT	N
TOTAL PARTS			
1	FREIGHT		
TOTAL MISC CHARGES			

PAY THIS AMOUNT	35559.90
AMOUNT OF CREDIT	
PAST DUE AFTER: 07-08-23	

Remit to: EMPIRE SOUTHWEST, LLC
 PO BOX 842381
 LOS ANGELES, CA 90084-2381

SERVICE INVOICE

INVOICE NUMBER: WO3A0008198

Invoice Date: 05-06-24

Due \$94,801.90

Make AA

Model D8T

Serial# 0FMC00829

Equip No 30215

Machine ID

Meter Reading 5.0

PSO/WO MRO4023

Customer #	PO #	Doc Date	Salesman	Division	Store	Terms
7550932	13851-30215	04-01-24	589	G	3A	2

Quantity	Item	Description	Unit Price	Extension
----------	------	-------------	------------	-----------

TOTAL PARTS SEG 03

TOTAL LABOR SEG 03
SEGMENT 03 TOTAL

REMOVE & INSTALL TILT CYLINDER

CUSTOMER COMPLAINT: REMOVE AND INSTALL TILT CYLINDER

CAUSE OF FAILURE: N/A

RESULTANT DAMAGE: N/A

REPAIR PROCESS COMMENTS: 4891 LEYVA

- REMOVED COVER
- REMOVED HOSES
- REMOVED CYLINDERS
- INSTALLED CYLINDERS
- INSTALLED CYLINDERS
- INSTALLED COVER

TRAVEL TO/ FROM MACHINE

CUSTOMER COMPLAINT: TRAVEL TO FROM MACHINE

CAUSE OF FAILURE: N/A

RESULTANT DAMAGE: N/A

REPAIR PROCESS COMMENTS: 4891 LEYVA

- CONTACTED CUSTOMER
- VERIFIED MACHINE LOCATION
- DROVE TO MACHINE IN MONAHANS

SERVICE INVOICE

INVOICE NUMBER: WO3A0008198
Invoice Date: 05-06-24

Due \$94,801.90

Make AA
Model D8T
Serial# 0FMC00829
Equip No 30215
Machine ID
Meter Reading 5.0
PSO/WO MR04023

Customer #	PO #	Doc Date	Salesman	Division	Store	Terms
7550932	13851-30215	04-01-24	589	G	3A	2

Quantity	Item	Description	Unit Price	Extension
----------	------	-------------	------------	-----------

REMOVE BOTTOM GUARD

CUSTOMER COMPLAINT: REMOVE AND INSTALL BOTTOM GUARD

CAUSE OF FAILURE: N/A

RESULTANT DAMAGE: N/A

REPAIR PROCESS COMMENTS: 4891 LEYVA

- USED CRANE TO SUPPORT BOTTOM GUARD
- REMOVED BOTTOM GUARDS
- CLEANED OUT ALL GUARDS
- ONCE WORK WAS COMPLETE USED CRANE TO SUPPORT BOTTOM GUARDS
- INSTALLED BOTTOM GUARDS AND SECURED

REMOVE & INSTALL TRANSMISSION

CUSTOMER COMPLAINT: - REMOVE AND INSTALL TRANSMISSION

CAUSE OF FAILURE: N/A

RESULTANT DAMAGE: N/A

REPAIR PROCESS COMMENTS: 4891 LEYVA

- LOCATED MACHINE
- REMOVED RIPPER SHANKS
- REMOVED RIPPER VALVE AND HOSES
- REMOVED PANELS
- REMOVED AXLES
- HAD CUSTOMER DRAIN TRANSMISSION OIL
- REMOVED TRANSMISSION BOLTS
- USED CRANE TO REMOVE TRANSMISSION
- CLEANED OUT CASE
- LOCATED NEW TRANSMISSION
- INSTALLED NEW TRANSMISSION
- INSTALLED DRIVE LINE

SERVICE INVOICE

INVOICE NUMBER: WO3A0008198
Invoice Date: 05-06-24

Due \$94,801.90

Make AA
Model D8T
Serial# 0PMC00829
Equip No 30215
Machine ID
Meter Reading 5.0
PSO/WO MR04023

Customer #	PO #	Doc Date	Salesman	Division	Store	Terms
7550932	13851-30215	04-01-24	589	G	3A	2

Quantity	Item	Description	Unit Price	Extension
----------	------	-------------	------------	-----------

- INSTALLED RIPPER MANI FOLD AND HOSES
- HAD CUSTOMER TOPP OFF FLUIDS
- INSTALLED AXLES
- INSTALLED RIPPER SHANKS
- RAN TRANSMISSION FILL CALIBRATION
- ENSURED NO LEAKS WERE PRESENT
- INSTALLED PANELS
- 2 6F- 4161 DOWEL N
- 2 8T- 4123 WASHER S
- 2 288- 3678 BOLT- HEX HEA S
- 1 CORE DEPOSIT N
- 1- CORE RETURN N

TOTAL PARTS 5

SEGMENT 02 TOTAL

REMOVE & INSTALL LIFT/ HOIST CYLINDER

CUSTOMER COMPLAINT: REMOVED AND INSTALL LIFT CYLINDER

CAUSE OF FAILURE: N/A

RESULTANT DAMAGE: N/A

REPAIR PROCESS COMMENTS: 4891 LEYVA

- REMOVED LIGHT BRACKETS
- REMOVED BOTTOM BOLTS
- REMOVED LIFT CYLINDER MOUNTS REMOVED LIFT CYLINDER

- HAD CUSTOMER TAKE CYLINDERS TO GET REBUILT
- LOCATED CYLINDER
- INSTALLED LIFT CYLINDER
- INSTALLED HOSES
- INSTALLED LIGHT BRACKET
- CONNECTED AND SHIMMED BOTTOM CYLINDER
- 1 3844149R D8T TRANSMISSION N
- 1 CORE DEPOSIT N
- 1- NO CREDIT N