

ESTIMATE VERSION 3 - POSTED TO FLEET

Updated at: 2024-10-28 07:45:07 -0500

Case Number:
Repair Order Number: 127731
Purchase Order Number: N/A
Service Advisor:
ETR: 10/9/2024 at 04:38 pm CDT

Customer: 55068	Unit Number: 1794
Address 55068	Asset: 2020 Peterbilt 389
Phone: N/A	Serial Number: LD274126
Fax: N/A	VIN: 1XPXDP9X9LD274126
Customer Number: IGH	Engine: MX-13
	Engine Hours: 1
	Odometer: 550861 Miles
	Warranty Start: 04/11/2019 12:00:00
	In Service: 5 Years 6 Months

1 Repair As Described [WARRANTY]					
Complaint:	Recall Campaign: [22PBB] Dana Front Axle Steer Arm Fasteners				
Correction:	* THERE WAS NO DAMAGE OR SIGNS OF A ISSUE WITH KNUCKLE BOLTS - REASSEMBLED AS REMOVED*				
		Quantity	Price	Core Price	Totals
Labor:			\$172.73	n/a	\$0.00
Parts:	10000180	BOLT -HEX	2.0		
	CM10045885	SEAL SERVICE KIT - FF FRONT	1.0		
	453869-8CHR	GASKET-HUB	1.0		
	CT05317	TIE-CABLE 50LB 15.5" BLK	5.0		
	W34-1161-060	BOLT-FINISHED HEX, M20	6.0		
	W34-1162-020	WASHER-METRIC, HARD	6.0		
	223030-873	CHV DELO SYNGEAR XDM 75W90 (	2.0		
	Parts Total				\$0.00
Additional Charges:	Shop Sup1, Service Shop Supplies	n/a	\$47.29	n/a	\$0.00
	Freight 1, Freight Charge - Parts Department	n/a	\$6.63	n/a	\$0.00
	Additional Charges Total				\$0.00
Operation Total:	\$0.00				

2 DIAGNOSTIC / TROUBLESHOOTING [WARRANTY]					
Complaint:	COMPLAINT ENGINE RUNS ROUGH				
Correction:	CHECK FLUID LEVELS AND TOP OFF COOLANT. OIL LEVEL OK. TEST DRIVE. CHECK FOR LEAKS. FIND NONE.				
		Quantity	Price	Core Price	Totals
Labor:			\$177.00	n/a	\$0.00
Parts:	1680226PE	O-RING	1.0	\$0.00	
	1682342PE	PIPE-OIL SUPPLY COMP RSL	1.0	\$0.00	
	1857669PE	SET-GASKET	1.0	\$0.00	
	1858032PE	SEAL-BONDED	1.0	\$0.00	
	2405076PE	FUEL INJECTION PIPE TO FUEL RAIL	2.0	\$0.00	

ESTIMATE VERSION 3 - POSTED TO FLEET

Updated at: 2024-10-28 07:45:07 -0500

Customer:	Unit Number: 1794
Case Number: 16345474	Asset: 2020 Peterbilt 389 VIN: 1XPXDP9X9LD274126

1923003PE	GASKET	1.0	\$0.00
LP34216	CLAMP-V, 5 INCH SPHERICAL	1.0	\$0.00
1827320PE	GASKET	1.0	\$0.00
K4122	KIT-HEX FLANGE CRIMPED NUT	1.0	\$0.00
1907399PE	GASKET-AIR INTAKE	1.0	\$0.00
1893478PE	SENSOR-TEMP AIR RSL	1.0	\$0.00
F69-1028-131	COMPRESSOR-HVAC SLIMLINE	1.0	\$0.00
W34-1158	BOLT-FLANGE HEAD, M16 X 2	8.0	\$0.00
HWC04514	BOLT-HEX M8-1.25X100 CL10.9 CAD	2.0	\$0.00
2134899PE	PIPE-COOLANT, COMPRESSOR	1.0	\$0.00
2102335PE	COOLANT PIPE	1.0	\$0.00
2405076PE	FUEL INJECTION PIPE TO FUEL RAIL	2.0	\$0.00
9210TRP	CLAMP-HOSE W/LINER #10	2.0	\$0.00
730395ATC	WASHER-SEALING	1.0	\$0.00
730393ATC	WASHER-SEALING #8	2.0	\$0.00
HE2308	HOSE-PUSH ON #12X25' RBR	3.0	\$0.00
1851381PE	CONNECTOR, 2 POLE	0.0	\$0.00
2118375PE	CLAMPING BLOCK, MX-13	1.0	\$0.00
2111441PE	GASKET, OIL PAN	0.0	\$0.00
1428308PE	CONNECTOR	1.0	\$0.00
P062STPA	RING-RETAINING	1.0	\$0.00
2104016PE	CLAMP	1.0	\$0.00
ETP-PL1362-4	UNION, PSH-LK, BRS, 1/4 TUBE	2.0	\$0.00
K1T-RPL25-20	HARDWARE-RPL CP	2.0	\$0.00
39655	GR. C-NE8 NYL INS LOCK NUT 1	2.0	\$0.00
D39106	GR.8HXCAPSCREW1/2-13X1-1/2	2.0	\$0.00
39705	HARDENED FLAT WASHER 1/2 SAE	4.0	\$0.00
EC3501	GAL RED 50/50 COOLA	3.0	\$0.00
CT05512	TIE-CABLE 120LB, 15.25" BLK	100.0	\$0.00
CT05317	TIE-CABLE 50LB 15.5" BLK	30.0	\$0.00
257000-990	DELO XLE SYN BLEND 10/30 BUL	48.0	\$0.00
ETP-4520	NON-CHLORINATED QUICK DRY BRAKE CLEANER - 12.5 OZ	6.0	\$0.00
2397569PE	OIL COOLER, MX-13, EPA17	1.0	\$0.00
2127357PE	SENSOR-PRESSURE, PRE TURBO	1.0	\$0.00
2173001PE	INSTALLATION KIT - MX13EPA17 LONG BLOCK	1.0	\$0.00
2027148PE	O-RING, 20.3X2.6	1.0	\$0.00
2234788PE	OIL FILTER ELEMENT	1.0	\$0.00
1922496PE	ELEMENT-OIL, CENTRIFUGAL	1.0	\$0.00

ESTIMATE VERSION 3 - POSTED TO FLEET

Updated at: 2024-10-28 07:45:07 -0500

	Unit Number: 1794				
Case Number: 16345474	Asset: 2020 Peterbilt 389 VIN: 1XPXDP9X9LD274126				
	2277129PE	FILTER-FUEL	1.0		\$0.00
	2154314PE	OIL PAN, COMPOSITE, REAR	1.0		\$0.00
	1863266PE	RING-SEALING	2.0		\$0.00
	2135209PE	FLANGE BOLT - M10X55	18.0		\$0.00
	2047414PE	GASKET SET, OIL MODULE	1.0		\$0.00
	1865847PE	O-RING, INJECTOR	6.0		\$0.00
	1638270PE	O-RING INJECTOR	6.0		\$0.00
	2127551PE	RING SEAL, INJECTOR	6.0		\$0.00
	1313122PE	BOLT-FLANGE M8X65 10.9	4.0		\$0.00
	1313120PE	BOLT-FLANGE M8X55	6.0		\$0.00
	Parts Total				\$0.00
Additional Charges:	Comp Diag, Computer Diagnostic Charge		n/a	\$150.00	n/a \$0.00
	Shop Sup1, Service Shop Supplies		n/a	\$845.31	n/a \$0.00
	Additional Charges Total				\$0.00
Operation Total:					\$0.00

3 Peterbilt Platinum Courtesy Inspection					
Complaint:	Peterbilt Platinum Courtesy Inspection				
Correction:	PERFORMED INSPECTION				
		Quantity	Price	Core Price	Totals
Labor:			\$0.01	n/a	\$0.00
Operation Total:					\$0.00

4 CLUTCH					
Complaint:		REPLACE CLUTCH AND INSTALL CLUTCH INSTALL KIT			
Correction:		DRILL OUT HOLE IN PTO FOR HELICOIL. HOLE HAD PULLED THREADS. INSTALL PTO AND SECURE.			
		Quantity	Price	Core Price	Totals
Labor:			\$177.00	n/a	\$0.00
Parts:	308925-82	EP 15.5, 1700 TORQ, DAMPER,	1.0	\$0.00	
	K2468	KIT-CLUTCH INSTALL	1.0	\$0.00	
	06-01093	SHAFT-CLU	1.0	\$0.00	
	06-00530	SHAFT	1.0	\$0.00	
	016122	fitting	1.0	\$0.00	
	016162	fitting	1.0	\$0.00	
	1/8-mro-s	adapter	1.0	\$0.00	
	48f4-2	adapter	3.0	\$0.00	
	Parts Total				
Additional Charges:		Shop Sup1, Service Shop Supplies	n/a	\$72.37	n/a
Operation Total:					\$1,175.60

ESTIMATE VERSION 3 - POSTED TO FLEET

Updated at: 2024-10-28 07:45:07 -0500

	Unit Number: 1794
Case Number:	Asset: 2020 Peterbilt 389 VIN: 1XPXDP9X9LD274126

	Parts	
	Shop Sup1	
	Taxes	
	Total	\$1,236.28

Notes:

[10/10/2024 at 07:44 am CDT] - Unit 1794 was checked in at Allstate Peterbilt of Superior. Arrival time: 10/10/2024 at 07:44 am CDT.

NOTE: YOUR UNIT HAS ARRIVED AT THE DEALERSHIPCase status set to Checked-in.

[10/10/2024 at 07:49 am CDT] - Approval Requested for the estimate version 1. Total \$150.00. Repair status set to Hold (auth).

[10/16/2024 at 12:03 pm CDT] - Good Afternoon Superior team,

Can you please provide us with a status update on this repair?

Thank you

[10/16/2024 at 12:10 pm CDT] - Long block just showed up

Jim Krivinchuk | Service Writer

Allstate Peterbilt of Superior

211 Hammond Ave, Superior, WI 54880

715-392-4440 ext 1217

Direct : 715-390-4669

jkrivinchuk@allstatepeterbiltgroup.com

[cid:image001.png@01DB1FC4.01AA4A30]

Find us on: allstatepeterbilt.com | Twitter | Facebook

Instagram | LinkedIn | YouTube

Sent via Email

[10/16/2024 at 12:16 pm CDT] - Thanks Jim, Please try to keep our team updated through Decisiv.

[10/21/2024 at 10:43 am CDT] - Good Morning Brian,

I just spoke to Jim about the order for a coolant manifold for this unit, do you have an ETA on this part?

Please reach out to our team if this needs to be expedited.

Thank you

[10/21/2024 at 11:05 am CDT] -

Sent via Email Reply

[10/25/2024 at 07:54 am CDT] - Asset is Ready. NOTE: UNIT IS COMPLETED AND READY FOR PICK UPCase status set to Complete (here).

	Unit Number: 1794
	Asset: 2020 Peterbilt 389 VIN: 1XPXDP9X9LD274126

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding and that this estimate does not include any applicable computer diagnostic hookup fees or charges. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it.

ESTIMATE