

Date	Time	Page
08/29/25	23:02:05 (B)	02
Account No.	Phone No.	Invoice No.

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
U007458	2100/ STERLING		X 2FZHATDC94AN18725		
	2100		04-03V-8857		
45747-30			I.D. BAR		1
45750-30			ID HARNESS #503		1
77038H-30			REAR DOOR WELD,		1

11300029 REP

REPAIR# 2 C US908 NA 03/14/25 03/20/25
 REPLACE MALFUNCTIONG 5K PSI GAUGE ON HOSE REEL
 R&R PRESSURE GAUGE
 46846D-30 PRESSURE GUAGE 1

11300029 REP

REPAIR# 3 C US908 NA 03/14/25 03/20/25
 REPLACE COLLAPSING RODDER PUMP HOSE
 HOSE CONNECTING WATER SIDE OF PUMP NEEDS REPLACED
 45824C-30 3" HOSE X 18" 1

11300029 REP

S
C

ALERT: If you are requested to modify any payment instructions, please do not act on the request. Contact the JJE Credit department via a known/verified phone number.

ALBANY	BILLINGS	CHICAGO	COLORADO	MONROE
518.407.3154	406.205.1491	312.829.1919	720.399.0095	704.289.5488

