

Invoice

BILL TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
6014	04/21/2026	\$19,183.02	05/01/2026	Due on receipt	

P.O. NUMBER
Truck# 207

ITEM#	DESCRIPTION	QTY	RATE	AMOUNT
Labor- Shop	Engine flywheel housing broken and transmission falling out of truck. Remove doghouse, guards ect and pressure washed engine and transmission. Aired up truck and moved into shop. Removed drivelines, transmission, oil pan, valve cover, rocker box, valvetrain, rear manifolds on cylinder head, rear geartrain, air compressor, starter, fuel pump, egr lines, water pipes, clutch, flywheel and flywheel housing. Found excess damage from original inspection including broken wiring, broken coolant tubes, broken battery cables, parts missing, ect. Decided to repair transmission in house to keep cost down because of extra damage. Disassembled front of transmission and repaired input shaft, clutch actuator, plates and bearing. Repaired bellhousing. Installed new clutch actuator and supply hose. Replaced damage coolant tubes. Built new battery cables and installed. Replaced missing tarp relay assembly on back of cab. Replace flywheel housing and reassemble. Installed rocker box, valve cover, rear manifolds, egr lines, air compressor, fuel pumps, power steering pump, ect with all new seals. Installed transmission with new clutch and actuator. Replaced damaged carrier bearing and reinstalled driveshaft. Perform all calibrations, testing and checks for proper operation.	82	)	11,070.00
113M/22986940	Flywheel Housing	1	)	1,347.38T
Freight		1	)	109.00T

ITEM#	DESCRIPTION	QTY	RATE	AMOUNT
113M/24817250	CRANKSHAFT SEAL	1		143.60T
113M/85148633	SEAL	1		107.24T
113M/976068	O-Ring	1		35.25T
113M/85022454	Clutch Cylinder	1		1,017.61T
113V/24976861	Clutch Kit	1		1,258.81T
113V/23239988	Bearing	1		79.14T
Labor- Contracted	Tow Bill	1		750.00
113M/949656	O-Ring	1		16.06T
113M/21007187	Gasket	1		31.53T
113M/22596885	Pipe- Coolant	1		62.98T
113M/23145328	Pipe- Coolant	1		70.17T
Freight		1		35.00T
113M/20992763	Air Hose	1		102.85T
113M/20483426	Input Seal- Transmission	1		60.97T
113M/20852765	Sealing Ring	4		73.36T
113M/22777560	Gasket	1		415.27T
113V/21780376	Sealing Ring	1		30.24T
113M/20850815	Gasket	1		61.55T
113V/11996	Gasket	4		39.28T
113M/21095721	Gasket	2		51.12T
113M/20978469	Ring	1		14.84T
113M/21095726	Gasket	1		41.45T
113M/60113828	Screw	6		212.40T
113M/60112885	Flange Screw	6		129.18T
113M/21293367	Gasket Seal- Oil Pan	1		198.76T
113M/1547253	Sealing Ring	1		46.03T
113M/967343	O-Ring	2		59.90T
113M/20841816	Gasket	2		59.74T
113M/992065	O-Ring	1		36.71T
113M/982508	Gasket	1		21.53T
113M/977030	O-Ring	1		34.11T
Freight		1		30.00T
Antifreeze	OAT 50/50 Extended Life Coolant	9		117.00T
Bulk Oil	15W-40 Synthetic Blend Engine Oil	9		151.65T
113M/21447682	Gasket	1		138.95T
24454-BX	Relay Module FW-REV 12VDC	1		127.59T
Brake Cleaner	18 oz Brake Cleaner	12		51.00T

ITEM#	DESCRIPTION	QTY	RATE	AMOUNT
EL720100	Black 2/0 .605" OD Battery Cable (ft)	10		74.90T
EL710102	Red 2/0 .605" OD Battery Cable (ft)	10		105.00T
84844	3/8" Stud 2/0 Battery Cable Lug	2		12.98T
84845	1/2" Stud 2/0 Battery Cable Lug	2		15.06T
86503	8-1 Ga Thick Heat Shrink Tube	2		13.72T
TDA/MCB206	Support- Carrier Bearing RPL35	1		113.54T

SUBTOTAL
TAX
TOTAL
BALANCE DUE

\$19,183.02