

UNIT #

MAKE

YEAR

MODEL

ENGINE NO.

SERIAL NO.

QTY	PART NUMBER	DESCRIPTION
1	15100-HW8	oil pump
8	91303-KFO	o rings
2	91313-MG7	o rings
2	91303-679	o rings
1	15133-HW2	oil pump drive chain
1	15401-HW2	oil pump sprocket
1	15315-HW8	oil Strainer gasket
1	91203-KCY	Seal
1	91305-KFO	O ring
1	91301-PTX	o ring
1	91314-PC9	O ring
1	91305-MG7	O ring
1	91361-473	O ring
1	91303-HW8	O ring
1	91302-HW8	O ring
1	91302-MB0	O ring
1	15412-KEA	oil filter
4	6N4-5-30	oil
TOTAL Parts		

RES.	BUS.	MEMO	LICENSE
			SPEEDOMETER 2057
<input type="checkbox"/> TUNE-UP <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> ADJ. CLUTCH <input type="checkbox"/> CK. CHAIN <input type="checkbox"/> FORK OIL <input type="checkbox"/> GEAR OILS <input type="checkbox"/>			

JOB CODE

trans slipping Check oil pressures
 Low oil pressure on transmission side
 10 Eng oil pressure 114 PSI @ 5000 RPM
 trans oil pressure 62 PSI should be 114 PSI
 5 Replace oil pump + o rings + seal
 chain + sprocket

\$995.49

Thank you

TOTAL LABOR

TOTAL PARTS

TAX

TOTAL

995.49

Ref. No. G 91510206