

Repair Order

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 15, 2026		DT			1 / 2

WO019266

DOUBLE TAKE ENTERPRISES

Unit 143	VIN 1NKDX4EX5DJ348143	ODOMETER 84924 MI
Description 143 - Tri Axle		ENGINE 4644 HR
Make Kenworth	Model T800	Year 2013
Engine 79562651	Last Cert. ()	

Activity Description		
Part #	Part Description	Quantity
1. Tilt Body Hydraulics		
	CK FOR HYRAULIC LEAK	2.00 HR
2. Transmission Assembly - Manual		
	NOISY	12.00 HR
GEAR LUBE 50W	GEAR LUBE 50W	20.00 QT
RXRTO16908LLPGTP	16908LL TRANSMISSION	1.00 EA
REMAN TRANSMISSION		
3. Clutch Assembly		
127760-50	BRAKE CLUTCH 1PC	1.00 EA
105C137	YOKE CLUTCH RELEASE	1.00 EA
308925-20 15.5 CLUTCH	EP 15.5, 1860 TORQ, VC	1.00 EA
4. REAR MAIN SEAL		
6609787CUM REAR	REAR MAIN SEAL CUMMINS	1.00 EA
MAIN SEAL		
5. Power Divider & Inter-Axle Differential - Rear Axle		
170-70-18X	STRAP KIT DRIVELINE	2.00 EA
250-70-18X	STRAP KIT UJOINT BRG(25)	1.00 EA
6. AIR TANK		
BW 280809N DOUBLE	DOUBLE CHECK AIR VALVE	1.00 EA
CHECK VALVE		

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 15, 2026		DT			2 /2
Activity Description					
Part #	Part Description				
7. AIR DRYER PURGE VALVE					
K022105BXW	PURGE VALV E ADIP&IS DRYRS				

Technician:

Authorized By:

DR#8751370

RG/RM-1-REPLACED SUCTION HOSE FROM DUMP PUMP TO HYDRO TANK

2-REPLACED TRANSMISSION WITH RECON, OLD ONE WAS SHOCK LOADED

3-REPLACED CLUTCH ASSEMBLY AND RESURFACED FLYWHEEL

4-REPLACED REAR MAIN SEAL

5-REPLACED POWER DEVIDER WITH USED OUT OFF 900

6-REPLACED DOUBLE CHECK VALVE

7-REPLACED PURGE VALVE

Proof Total: 7,724.97

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Aug 13, 2025		DT			1 / 2

WO017981

DOUBLE TAKE ENTERPRISES

Unit 143	VIN 1NKDX4EX5DJ348143	ODOMETER 72962 MI
Description 143 - Tri Axle		ENGINE 3886 HR
Make Kenworth	Model T800	Year 2013
	Last Cert. ()	Engine 79562651

Activity Description		
Part #	Part Description	Quantity
1. Tires - Drive		
		1.50 HR
2. SEAL		
		1.50 HR
GEAR LUBE 75-90	GEAR LUBE 75-90 / HDS 7590 35	2.00 QT
393-0173	SEAL VOYAG ER	1.00 EA
39874 33MM WHEEL NUT	WHEEL NUT 33 MM	1.00 EA
AUT201.6247 WHEEL STUD	TRUCK WHEEL STUD	1.00 EA
132993ETN	DOWEL CONE WHEEL STUD	1.00 EA
GKT1008 /BLUE AXLE GASKET METAL INSERT	BLUE METAL GASKET	1.00 EA
42320IMP TEFLOCK	NUT 5/8 N/F 18 SAE TOP LOCK	8.00 EA
AUT201.7526 AXLE STUD	AXLE STUD	8.00 EA
3. Wheel Bearings - General		
		1.50 HR
HYTSET430 BEARING SET	BEARING SET 430	1.00 EA
HYTSET429 BEARING SET	BEARING SET 429	1.00 EA
4. Radiator - Engine Cooling System		
		8.00 HR
<i>leaking</i>		
COOLANT 50/50	COOLANT 50/50	8.00 QT
HEATHWOOD 2400208LW/RADIATOR	OS-RAD 08-19 KENWORTH T-800,14-19 T880	1.00 EA

Technician:

Authorized By:

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Aug 13, 2025		DT			2 /2

RG--1--REPLACED WITH USED TIRE, REPLACED ONE WHEEL STUD
2--REPLACES WHEEL SEAL
3--REPLACED BEARINGS AND RACES, AXLE STUDS AND NUTS
RM/RG--4--REPLACED RADIATOR WITH NEW

Proof Total: 1,584.86

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Jun 7, 2023		DT			1 / 2

WO013086

DOUBLE TAKE ENTERPRISES

Unit 143	VIN 1NKDX4EX5DJ348143	ODOMETER 35911 MI
Description 143 - Tri Axle		ENGINE 1721 HR
Make Kenworth	Model T800	Year 2013
	Last Cert. ()	Engine 79562651

Activity Description			
Part #	Part Description	Quantity	Unit
1. Engine Assembly		0.50	HR
CK FOR WEEDEATER NOISE			
2. Engine Mountings - Frame		3.50	HR
REPLACE ENGINE MOUNTS			
05-16401 FRT ENGINE MOUNT	FRT ENGINE MOUNT ISX 2013	2.00	EA
11681TBG REAR ENGINE SUPPORT	REAR ENGINE SUPPORT	1.00	EA
W34-1095-070 BOLT FLANGE M16X2X7	FRONT ENGINE RLANGE BOLT	2.00	EA
17773IMP BOLT 3/4-16 X 5	3/4-16 X 5 BOLT	2.00	EA
42321IMP NNUT LOCK 3/4-16STOP	LOCK NUT STOP 3/4-16	2.00	EA
76518IMP	WASHER 3/4 FLAT SAE	2.00	EA
3. Clean DPF Filter		5.00	HR
REMOVE AND CLEAN			
2871453CUM	GASKET DPF 13 1/4	1.00	EA
DO1X007784	4" PREFORMED BAND CLAMP	1.00	EA
DO1X007785/5 INCH BAND CLAMP	5 INCH BAND CLAMP	1.00	EA
2866337CUM	5" EXHAUST GASKET	2.00	EA
1844896PE 4" THIN GASKET DPF,DOC	GASKET-EXHAUST	1.00	EA
4. Cab Windshield Wiper & Washer		0.50	HR
REPLACED BLADES			
31-18	WIPER BLAD E 18IN.	2.00	EA

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Jun 7, 2023		DT			2 /2

Activity Description	
Part #	Part Description
5. EXHAUST PIPING/FLEX/T/Y/ELBOW/STRAIGHT	
<i>REPLACED LOWER FLANGE TO STACK</i>	
AUT562.U15882A	5" FLARED FLANGE
FLARED 5" FLANGE	
D01X007785/5 INCH	5 INCH BAND CLAMP
BAND CLAMP	
6. Tires - Drive	
<i>REPLACE 4LI/O</i>	

Technician:

Authorized By:

RM-1-INSPECT FOUND MOTOR MOUNTS BAD

2-REPLACE ENGINE FRONT AND REAR MOUNTS

3-CLEAN DPF FILTER. RD, REMOVED, RM RE-INSTALLED

RD-4-REPLACE WIPER BLADES

RM-TAG AXLE KING PINS STARTING TO SHOW WEAR

RM-5-REPLACED LOWER STACK FLANGE

RM-6-REPLACED 4LI/O WITH USED 4LI-AD394AB8
AD394AO3

Proof Total: 1,342.76

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Mar 7, 2022		DT			1 / 1

WO010519

DOUBLE TAKE ENTERPRISES

Unit 143	VIN 1NKDX4EX5DJ348143	ODOMETER 10 MI
Description 143 - Tri Axle		ENGINE 1 HR
Make Kenworth	Model T800	Year 2013
	Last Cert. ()	Engine 79562651
Activity Description		
Part #	Part Description	
1. Engine Assembly		
R&R ENGINE, TOP OFF FLUIDS		
RXDR6969RXCUM	ISX 15 10 B RECON ENGINE	

Technician:

Authorized By:

DIESEL SOLUTIONS

DS INVOICE 2002

KW INVOICE T00205601805605

Proof Total:

42,918.77