

SAME AS BELOW

Sold To	Ship Via	Purchase Order
	P.S.T. Number	F.S.T. Number
		Salesperson BRM

STK#/FLEET#	Description	HRS	PIN/EIN	WARRANTY DATE	HRS
A001828	2012 CH MT585D TRA MT585D	2385	C143052		
SEGMENT# 1 C 688	NA	05/28/19	05/28/19	05/30/19	

AC
CORRECTION:

Charged system with nitrogen and sprayed down compressor and lines. Couldn't find a leak so pulled off roof and found that the evaporator was leaking. Removed evaporator and then installed new one. Vacuumed system down and charge system up. Noticed that the block cross over gasket was leaking. Drained coolant and resealed block plate. Filled up with coolant and ran to make sure plate wasn't leaking

3 pounds R134A

ACW1796890	GASKET	1		
EDE711044	FITTING	1	N	
FRT	FREIGHT	2		
F6262	PLIERS-6-1	3		
P048AF6P	COOLANT-FC	3		
	COOLANT-FC EG CN			
R134A	FREON	3		
3909742M91	EVAPORATOR	1	N	
4355270M1	PLUG	1	N	
72454647	SEAL	5	S	
	SEAL			
72454650	O-RING	2	S	
	O-RING			

10300007

SEGMENT TOTAL==>

STK#/FI FFT#	HRS	PTN/FTN	WARRANTY DATE	HRS
--------------	-----	---------	---------------	-----

CONTINUED ON PAGE 02

MT585D

***** WORK ORDER TOTALS *****

PARTS

LABOR

SHOP SUPPLIES

A/R CHARGE

1561.07

Remit to:

[Print](#)

[Email PDF](#)

[Text PDF](#)

[Multimedia](#)

[Parts & Labor](#)

[Work Order Preview](#)



[G/L Details](#)

[Back](#)