

QTY.	PART NO. AND DESCRIPTION	PRICE
1	73-4L152C Long Block	
1	1000 Fuel Filter	
1	491A Oil Filter	
1	5319 Fuel Filter	
6	gal Lifetime Antifreeze	
3 1/2	Freon	
1	Ester Oil	
1	Tube Chassis Grease	
3	5" SS Band Clamp	
3	ft 5" SS Flex	
1	89447 DYC Tensioner	
1	1979642 Pulley	
1	D84-1000-3061460 Belt	
1	D84-1000-3082370 Belt	
1	KS 14-256 Fan Hub Rebuild	
1	2639001 Harness Assy	
2	GX UT-JCFX-0808 Fitting	
15	GX DUT-08X250RL Hose	
3	5900196 Yellow Paint	
3	1656170 Plug	
1	2769507 Hose	

(MAY BE CONTINUED ON OTHER SIDE)

TOTAL PARTS

5/13

4/13

TOTAL ACCESSORIES

DESCRIPTION OF WORK

AMOUNT

☐ LUBE ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE-UP ☐ TRANS. ☐ DIFF.

Check engine not rotating. Found #4 main bearing spun. R&R engine and transmission. Removed transmission and rear structure. Removed all necessary parts from old engine and re-installed on new long block. Re-install new engine and transmission. Hooked up all electrical. Installed new engine harness. Replaced all heater hoses and replaced transmission

LITERS/GALS. OF GAS @

40 LITERS/QTS. OF OIL @ 5.10

kg/LBS. OF GREASE @

36 lb. transmission fluid

TOTAL LABOR

TOTAL PARTS

ACCESSORIES

GAS, OIL AND GREASE

SUBLET REPAIRS

EPA / WASTE DISPOSAL

Shop Supply

TOTAL

THANK YOU

3898102

