

RECEIVED

JUL 02 2026

Serial Number	Unit Number	Make / Model	Year	License Number	Mileage
1XP5DB9X27D692741	172	PETERBILT/379	2007		1

OPERATION 2

COMPLAINT: REPAIR PER ESTIMATE

CORRECTION: OTHER MNT REPAIR-TOTAL VEHICLE-TOTAL VEHICLE-ACCIDENT
Labor Total --

3585L	HOOD SIDE 379 LH	1
4333L	LH HOOD TOP PANEL-37	1
3577L	LH INNER STRUCTURE-37	1
4905L	FENDER LH ALUMINUM-379	1
RXRF31S-950	BATTERY GROUP 31, 950	4
CXRF31S-950	CORE BATTERY (CORE CHA	4
RF1506080	FENDER LINER	1
RF657081749	8.5" OFF SET MOUNT CON	1
15-06691	FENDER FLAPS	2
MATERIAL	MATERIAL PAINT	1

Parts Total --
Total Operation 2 -- 13,054.35

CONTINUED

Customer Copy

ACTIVITY	QTY	RATE	AMOUNT
SHOP SUPPLIES	1		
SHOP SUPPLIES FEE			

ENGINE HAS OEM CATERPILLAR PISTONS/
DOES NOT HAVE LOW COMPRESSION KIT.
LINERS LOOKED GOOD AND HAD GOOD
CROSSHATCH MARKS, IT DOES LOOK AS IF
ENGINE WAS REBUILT RECENTLY.

ALL PARTS USED WERE PULLED FROM
SWAGGINS PRE ORDERED PARTS AND THEY
HAVE ALL BEEN REORDERED AND CHARGED
ON THIS INVOICE.

SUBTOTAL	
TAX (9.8%)	
TOTAL	12,001.81
PAYMENT	

TOTAL DUE	\$0.00
-----------	--------

THANK YOU.

DATE
09/22/2022

PLEASE PAY
\$0.00

MAKE-MODEL
PETERBILT

SERIAL-VIN
1XP5DB9X27D692740

MILES-HOURS
1304292 UNIT # 700

ACTIVITY	QTY	RATE	AMOUNT
parts KIT HEAD BOLT MCBC15HBK	1		
parts KIT EXHAUST HARDWARE MCBC15ESK	1		
parts HEAD GASKET KIT MCBC15213	1		
parts SPACER PLATE M-6I4421	11		
parts ROTELLA 15W40	1		
parts OIL FILTER 1R1808 CATERPILLAR OIL FILTER	1		
parts CYLINDER HEAD STAGE 2 MCB2239250A STOCK HEAD PER BRAD	12		
parts ANTIFREEZE ELC 50/50 OAT	1		
LABOR REPLACED CYLINDER HEAD FOR HAVING CRACKS BETWEEN VALVES. HEAD GASKET WAS BLOWN BETWEEN CYLINDERS 1 & 2 ENGINE HAS BEEN RECENTLY OVERHAULED SO CUSTOMER JUST WANTED TO REPLACE HEAD AND HEAD GASKET AT THIS TIME.	1		
LABOR PROGRAM ECM			