

Invoice

Date	Invoice #
10/20/2021	24570

Keep !!!

truck	VIN #	Engine	Engine #	Miles
KW	BS190436	3406B	3ZJ21280	236963
Quantity	Description			Amount
35.00	check out for pushing oil out dipstick, has excessive blow-by, remove cylinder head, find #6 piston cracked with hole, remove and replace all cylinder kits, replace rod and main bearings, replace cylinder head, test nozzles, replace all injector nozzles, install rear axle shocks			
6.00	rod bearing			
1.00	head set			
2.00	pan gasket			
2.00	thrust bearing			
6.00	cyl kit 0R3783			
1.00	rebuilt cylinder head			
7.00	main bearing			
1.00	pipe nipple			
1.00	O ring			
1.00	O ring			
6.00	nozzle			
1.00	water filter			
1.00	thermostat			
1.00	oil filter			
11.00	15/40 Shell			
3.00	1 1/2 stick hose			
2.00	shock			