

INVOICE DATE 08-05-26

REPAIR ORDER NUMBER

>>> ES27744 <<<<

CUSTOMER NAME

NUMBER h6245e

PHONE

P.O. NO.

COMPLETE 07-31-26

OPEN 07-30-26

SERIAL NO. 2NK5LJ0X5SM179673

UNIT NO. 179673

YEAR/MAKE/MODEL - 2025 Kenworth T480

ENGINE/MODEL/SERL PX-9 99331491

TRNS/MODEL/SERL -

RXLS MODEL/SERL -

SELL DLR

ENGINE - 3368.0

MEMO Hopkinsville Solid Waste 2708878556

SVC WTR MXW*KNB

MILEAGE 25477

LICENSE

CPL/ARRG

R RATIO

TAG #

DEL MILE

DEL DATE 09-26-25

PAGE 2

REVIEW FOR REPAIR ORDER - ES27744

1 Recall Campaign: [01088] TIB 01-088: T280/T380/T480 Evaporator Core

Failure Emissions Recall (OPEN) Proactive

TYPE SWP 100 %

CAUSE: Got AC line but need dryer and it had to be ordered.

CORRECTION:

TOTAL LABOR

TOTAL PARTS

646.00

379.84

OVERTIME HOURS 0.70

BRETT BOWMAN 11435 07-30-26

13:38 14:01

PAGE 3

REVIEW FOR REPAIR ORDER - ES27744

IAN HELDT 10852 07-31-26

11:45 12:00

IAN HELDT 10852 07-31-26

12:28 14:17

IAN HELDT 10852 07-31-26

1.5 14:17 15:30

1 1 P F50-3211-100

LINE - A/C SUCTION

361.83

EVE23139 2 1 P 84032985

RECEIVER DRYER-KIT SVC

18.01

2 CONDITION VOIDED - OPERATION MOVED TO REPAIR ORDER ES27779.1

ES27744 WARRANTY REC PACCAR 2630316 -1,025.84

Service Warranty Labor 4620300 646.00

Parts Warranty RO 4800300 379.84

PLEASE PAY THIS TOTAL 2200300 0.00

REVIEW FOR REPAIR ORDER - ES27744

PAGE 4

REPAIR ORDER - ES27744 NOTES