

INVOICE - CUSTOMER COPY

This form is an itemized list of repairs and is part of the original Repair Order. This Repair Order Continuation is subject to all of the terms and conditions of the original Repair Order.

Page 1

Work Order No.
93363

Make	Model	Year	Odometer	License No.	State	Color	Trim	Vehicle No.	In-Serv. Date	Stock No.
IN	QX56	11	70,702	SOLDIT	IA	Whit		JN8AZ2NC1B9	000083	8/19/10
Cust. No.	Contact			Day Phone No.		Extension		Evening Phone No.		Extension
GATH02										
Service Consultant				Labor Rate				Alternate Phone No.		Extension
DAVID GROOMS										
Tag	Wait	Wash	Estimate No.	Open Date	Promise Date	Time	Work Completed Date	Close Date		
2700	No	Yes		6/11/14	6/11/14	16:00	7/14/14			

01 VEHICLE TOWED IN, CUST. STATES, ON HARD ACCEL CAR WILL BUCK & THE SERVICE ENGINE SOON LIGHT CAME ON.
SEE NOTES FOUND P0524, P0011, P0021. PER TECHLINE, INSP LOWER OIL PAN, TIMING GUIDE & METAL FOUND. -RPL LONG BLOCK.

ENGINE MECHANICAL-A1000

Add-On? Tech
Yes DAME07

Labor ***** Factory

Parts	Qty	Each	Parts	Factory
ENGINE-BARE-10102-1LA0A	1		*****	Factory
GASKET-MANIFOLD TO C-14035-1LA0A	8	ASR	*****	Factory
GSKT-MAN EXHAUS-14036-1LA0A	2	ASR	*****	Factory
GASKET-ADAPTER-16175-1LA0A	1	ASR	*****	Factory
MOBIL OIL-BULK5W30	7		*****	Factory
PUMP ASSY-WATER-21010-7S000	1	ASR	*****	Factory
GASKET-WATER PUMP-21014-7S000	1	ASR	*****	Factory
THERMOSTAT-21200-1LA0A	1	ASR	*****	Factory
COIL ASSY - IGNITION-22448-1LA0B	1		*****	Factory
CLIP-01553-09321	8	ASR	*****	Factory
NISSAN LONG LIFE COO-999MP-L25500P	6		*****	Factory
POWER STEERING FLUID-999MP-AG000P	2		*****	Factory
COOLANT FLUSH KIT-5901	1		*****	Factory

VERIFIED CUST CONCERN, FOUND P0524, P0011, P0021. INSPECTED INT. V. TIMING W/ SOLÉNOID @ 0 DEGREES, N/G. TIMING CHAIN ISSUES. CHECKED P0524 W/ OIL PRESSURE GAUGE, N/G. 12 PSI @ IDLE. VEHICLE HAS OIL PRESSURE ISSUES ALONG W/ OIL CONSUMPTION ISSUES. 1 QT LOW AFTER 700 MILES. INSPECTED FOR SLUDGE, OK AT THIS TIME. PER TECHLINE, REMOVED LOWER OIL PAN, TIMING GUIDE & METAL FOUND & REMOVED FRONT TIMING COVER TO CHECK TIMING CHAIN. VEHICLE TIMING CHAIN REQUIRES TSB. WITH OIL PRESSURE CODE & CONSUMPTION. REPLACE LONG BLOCK PER TECHLINE. REPLACEMENT ENGINE FILLED WITH WATER & RUST. ORDERED ANOTHER REPLACEMENT ENGINE, SAME ISSUE. ORDERED ANOTHER ENGINE & FOUND WATER PUMP DAMAGE. REPLACE WATER PUMP & INSTALLED ENGINE. BURPED COOLING SYSTEM & PERFORMED COOLANT SERVICE TO REMOVE ANY REMAINING DEBRIS FROM WATER PUMP. PERFORM IAVL & CLOSED THROTTLE. RECHECK, OK AT THIS TIME.

* Totals Amount *
* Total.....: No Charge Customer*

Page 1

Authorization: I hereby authorize the repair work to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs.
Disclaimer of Warranties: The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE x