

INVOICE

18650

Invoice from History

Printed Date: 09/15/2026

Work Completed: 09/19/2025

2015 Kenworth - Cummins ISX

Lic # :

Odometer In : 0

Unit # : 50

VIN # : FJ454668

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Clutch	1.00		1,133.29	R&R clutch, service flywheel. R&R coolant	15.00	1,950.00
Bearing Pilot	1.00		26.32	tee.		
CLUTCH BRAKE	1.00		39.87	Shop Supplies		13.30
Coolant	2.00		28.00	Write off Bankrupt		-3,290.05
Coolant Tee	1.00		56.41			
Exhaust CLamp	2.00		29.34			
Flex Pipe 5" Galvanize	1.00		13.52			

[Payments -]

Labor:	-1,326.75
Parts:	1,326.75

Sub:	0.00
Tax:	0.00
Total:	\$0.00
Bal Due:	\$0.00

Vehicle Received: 9/12/2025

Customer Number : 2731

Signature _____

Date _____

INVOICE

18220

Invoice from History

Printed Date: 09/15/2026

Work Completed: 06/05/2025

2015 Kenworth - Cummins ISX

Lic # :

Odometer In : 0

Unit # : 50

VIN # : FJ454668

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Coolant	1.00		12.35	R&R front main seal, LFD brakes, drum, RRD brakes, drums, LRD slack adj & adj all brakes. Repair coolant leak on back of engine. Replace seal in power steering box.	12.00	1,560.00
Automatic Transmission Fluid	0.50		15.88			
Brake Shoes	2.00		162.30			
Brake Drum	2.00		242.36			
Slack Adjuster	1.00		137.48			

[Payments - Credit Card - \$2,158.03]

Labor:

Parts:

Sub:

Tax:

Total: \$2,158.03

Bal Due: \$0.00

Vehicle Received: 6/5/2025

Customer Number : 2731

Signature

Date

INVOICE

17140

Invoice from History

Printed Date: 09/15/2026

Work Completed: 08/07/2024

2015 Kenworth - Cummins ISX

Lic # :

Odometer In : 100656

Unit # : 50

VIN # : FJ454668

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Air Charge Cooler	1.00		1,066.64	R&R charge air cooler and wash radiator. Run overhead. R&R outlet nox sensor. Do cut out test on truck.	8.00	1,040.00
Outlet Nox Sensor	1.00		623.24			

[Payments - Credit Card - \$2,811.84]

Labor:

Parts:

Sub:

Tax:

Total: \$2,811.84

Bal Due: \$0.00

Vehicle Received: 8/7/2024

Customer Number : 2731

Signature

Date

INVOICE

16214

Invoice from History

Printed Date: 09/15/2026

Work Completed: 01/03/2024

2015 Kenworth - Cummins ISX

Lic # :

Odometer In : 0

Unit # : 50

VIN # : FJ454668

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Rear End Dif	1.00		1,793.28	R&R Rear End and Yoke	5.00	650.00
75/90 synthetic OIL	4.00		173.60			
Silicone Gasket Maker	1.00		27.45			
Yoke	1.00		368.19			

[Payments - Credit Card - \$3,127.10]

Labor:

Parts:

Sub:

Tax:

Total: \$3,127.10

Bal Due: \$0.00

Customer Number : 2731

Vehicle Received: 1/3/2024

Signature

Date

INVOICE

17915

Invoice from History

Printed Date: 09/15/2026

Work Completed: 03/18/2025

2015 Kenworth - Cummins ISX

Lic # :

Odometer In : 0

Unit # : 50

VIN # : FJ454668

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Water Pump	1.00		519.91	Outside Labor: Counterbore Repair		1,761.50
Seal O Ring	1.00		14.35	Cut Counter bores. Inframe overhaul. R&R	60.00	7,800.00
Oil Pump	1.00		909.00	water pump. R&R #6 Injector.		
Oil Filter	1.00		59.29			
Fuel Filter	1.00		68.25			
Injector	1.00		1,660.00			
High Temp Screw	12.00		105.00			
Inframe Kit	1.00		3,500.00			
Cylinder Head	1.00		4,687.50			
15W 40 Oil	13.00		312.00			
Coolant	15.00		210.00			
Piston Cooling Nozzle	6.00		214.80			

[Payments - Check - \$14,000.00, Credit Card - \$8,416.21]

Labor:

Parts:

Sub:

Tax:

Total: \$22,416.21

Bal Due: \$0.00

Vehicle Received: 3/18/2025

Customer Number : 2731

Signature _____

Date _____