QTY.	PART NO.	DECRIPTION	PRICE
1	N/SRTL018913RX	Transmission	
1	N/SRTL018913RX-C	Core	
(1)	N/SRTL018913RX-C	Returned	
1	MS09594	Oil Cooler	
~~2~~	~~[illegible]~~	~~Hose~~	
1	BCA306DDNC	Bearing	
1	BWE200316d PD	Sleeve	
1	BWE246089 PD	Insert	
12	CATOT08768	Bolt	2
5	CATID4703	Bolt	2
1'	DCW773-#LD	SplitLoom	
2'	DCW774-#	SplitLoom	0
1	DET23519651	Seal w/ Ring	
1	DET5100532	Flywheel Plate	
12	DET8929795	FlywheelBolt	4
1	FRT02-1263I-00#SS	ClutchShaft	
1	FRTde-23464-00 SS	Sensor	
1	FRTB5920008 SS	Sensor	
1	FRTFRE1020-000 SS	Hose	
1	FUL15900	Gasket	
1	FUL4305230 SS	Cover	
1	FUL4305294	Gasket	
1	FUL4308226 LD	Gasket	
1	HYD 2901-8-8	Elbow	
		Total	

FAX:

EMAIL:

TMC recommends lug nuts be rechecked between 50/100 miles after service.
TMC recommends lug nuts be torqued to 450-500 FT LBS. Semi Truck Tires...

Driver Signature:

Not Responsible For Loss or Damage to Cars or Articles Left in Cars in Case of Fire, Theft or Any Other Cause Beyond Our Control.

ADDRESS

DATE 02/26/26 A.M. P.M.

CITY STATE PHONE

YEAR AND MAKE	TYPE OR MODEL	VIN NO.	ON CLOCK
Freightliner	Coronado	3ALXFBCG0GDHA2809(1)	EFS
ODOMETER	LICENSE	HOURS / UNIT # 18924	OFF CLOCK

Shop Service

Removed both halves of the rear driveshaft. Disconnected all electrical plugs + secured it out of the way. Removed rear support bar from transmission. Disconnected transmission cooler lines + moved out of the way. Disconnected clutch arm from thru-shaft. Unbolted all bell housing bolts. Removed transmission. Found oil coating inside of flywheel housing. Removed transmission oil cooler + rear main seal. Installed spacer fork behind throw-out bearing. Unbolted + removed clutch assembly + flywheel. Cleaned flywheel housing + flywheel.

Total

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

PRINT:

X Signature

	Scan Tool/Tire Disposal
	Gas/Oil/Grease
	Miscellaneous
CASH	Freight/Storage
CC	Subtotal
CK #	Tax
	Total Amt. 12,224.15

THANK YOU, WE APPRECIATE YOUR BUSINESS!

McLEOD'S – 99660